

2.—RETURN of DEFECTS found on the INSPECTION of BOILERS and FITTINGS in the OTAGO DISTRICT during the Financial Year ended the 31st March, 1892.

Description.	Dangerous.	Ordinary.	Total.	Remarks.
Portable (17/4/91)	...	2	2	Through bar-stays corroded.
Tubular (20/4/91)	...	1	1	Four new stays and gear.
Portable (22/4/91)	...	...	...	No steam-gauge.
Tubular (23/4/91)	...	...	...	Patch on bottom.
Tubular (24/4/91)	...	...	...	Two patches on bottom.
Portable (25/4/91)	...	...	...	No steam-gauge.
Portable (28/4/91)	...	...	...	Crack in fire-box to be drilled out ; two mud-holes to be patched up ; new bottom-cock gauge- glass.
Portable (19/5/91)	...	...	...	
Portable "	...	...	...	
Portable "	...	...	...	
Traction (25/5/91)	1	...	...	Two pieces to be cut out of fire- box and patched.
Cornish tubular (25/5/91)	...	...	...	Ring round furnace tubes.
Cornish (25/5/91)	...	...	...	Manhole to be made larger.
Portable (26/5/91)	...	...	...	Mudhole to be cut to get at crown of portable.
Portable (28/5/91)	...	...	...	Two mud-doors to be fitted to portable.
Portable vertical (4/6/91)	...	...	...	Patch at bottom of outer D shell.
Portable vertical (5/6/91)	...	...	...	Patch at feed drum.
Cornish (8/6/91)	...	...	...	Patch in furnace mouth.
Portable (25/6/91)	...	...	...	Patches at two mudholes.
Tubular (11/7/91)	...	...	...	Patch on bottom at blow-off.
Portable (13/7/91)	...	...	...	Mudholes all to be patched.
Portable (16/7/91)	...	...	...	No steam-gauge.
Longitudinal tubular (20/7/91)	...	...	...	New dog-stay.
Traction (23/7/91)	...	...	...	New steam-gauge.
Tubular (25/7/91)	...	...	...	Patch on bottom.
Vertical (13/8/91)	...	...	...	Fore-part of fire-box renewed.
Portable (29/8/91)	...	...	...	Two mudholes to be patched.
Vertical (26/10/91)	...	...	...	Patch at feed-check and on mud- hole.
Portable (13/11/91)	...	...	...	Patch at mudhole.
Portable (8/1/92)	...	...	...	Bar-stay in steam-space; crack in fire-box to be drilled out.
Portable (9/1/92)	...	...	...	Extra dog across crown of fire-box.
Tubular (14/1/92)	...	...	...	New gauge-glass.
Portable (19/1/92)	...	...	...	New steam-gauge; new bar-stay to steam-space.
Portable (22/1/92)	...	...	...	One new bar-stay in steam-space.
Portable (26/1/92)	...	...	...	Two patches in fire-box, new tubes, and new steam-gauge.
Tubular (29/1/92)	...	...	...	Two new tube-plates.
Portable (8/2/92)	...	...	...	New steam-gauge to be got.
Portable (18/2/92)	...	...	...	One mudhole to be patched.
Portable, No. 5758 (25/4/91)	...	...	...	Cylinder-saddle and blow-off to be repaired.
Vertical, No. 5773 (6/7/91)	...	...	...	Mudholes to be repaired.
Portable, No. 5494 (18/8/91)	...	...	...	Ring round manhole.
Portable, No. 5682 (20/8/91)	...	...	...	Water-gauges all bad.
Vertical tubular, No. 6019 (31/8/91)	...	...	...	Ash-pit bad, to be repaired.
Portable, No. 5108 (16/9/91)	...	...	...	Crack in fire-box repaired.
Tubular, No. 5993 (17/2/92)	...	...	...	Mudhole cut; two new rows of tubes.
Egg-end, No. 5316 (27/2/92)	...	...	...	Small patch at end.
Tubular, No. 5945 (3/4/91)	1	...	1	Bottom of shell out, flue come down 1½ in., and showing frac- ture through oil.
Tubular, No. 5329 (24/10/91)	...	...	...	Found joints all blowing-out ; top of boiler and rivets leaking.
Vertical tubular, No. 5562 (26/10/91)	1	...	1	Tube-plate cracked, and has been repaired.
Longitudinal tubular, No. 5308 (28/10/91)	1	...	1	Found two plates with lamination, two pieces to be cut out and plate renewed.
Vertical tubular, No. 5147 (12/11/91)	1	...	1	New tube-plate put in and new new set of tubes.
Portable, No. 5351 (23/2/92)	...	1	1	New set of tubes.
Portable, No. 5364 (23/2/92)	...	1	1	Water-gauges all bad.