The major slip adjacent to No. 3 pipe-line continued to show movement, and it was not until the latter part of the year that a removal of the lower part of the slip was commenced.

During January, February, and March, the opportunity was taken to completely overhaul No. 3 main machine. This maintenance work had had to be postponed from the previous year owing to the power situation. In conjunction with this overhaul No. 3 penstock, 3,450 ft. in length and with a diameter varying from 78 in. to 66 in., was sand-blasted and painted internally with coal-tar paint. A roading alongside the penstock had been built to facilitate this work.

Extensive alterations were made to the test switches on the control board at the Tuai Power-station. New networks were fitted to Nos. 3 and 5 machine voltage-regulators. The governor-locking solenoid and associated equipment of both Nos. 4 and 5 machines was removed.

Satisfactory service was obtained from all machines. Generating-running times were as follows for the year:—

		Time on Load.		Time Idle.		Time under Repair.		
	Generator No.	Hours.	Percentage.	Hours.	Percentage.	Not in Demand (Hours).	In Demand (Hours).	Percentage Availability for Service.
1 2 3		7,061 7,086 5,637	$ \begin{vmatrix} 80.39 \\ 80.67 \\ 64.17 \end{vmatrix} $	Tuai 1,388 1,429 1,223	15.80 16.27 13.92	$\begin{vmatrix} 333 \\ 265 \\ 1,855 \end{vmatrix}$	$\begin{array}{c} 2\\ 4\\ 69 \end{array}$	96·19 96·94 78·09
4 5		5,870 5,840	$66.83 \\ 66.49$	Piripau 2,486 2,473	$\begin{array}{c c} 28 \cdot 30 \\ 28 \cdot 15 \end{array}$	424 421	4 50	$95 \cdot 13 \\ 94 \cdot 64$

Mangahao Power-station.—The rainfall for the year at No. 1 dam was 110·26 in., compared with 188·74 in. and 198·05 in. in the previous two years. At No. 2 dam the rainfall was 104·29 in., at No. 3 dam 79·55 in., and at the power-house 47·94 in.

The annual load factor dropped to 46 per cent. on a maximum load of 21,300 kW.

Extensive cleaning and painting of steelwork at all dams was carried out.

On 24th November the surge-chamber gates tripped, due to a sustained overload when Tuai tripped out, and the pipe-lines emptied.

All five turbine governors were completely overhauled and the oil renewed.

Two more sets of bronze buckets were received. One set was fitted to No. 3 turbine, and this completed the change to new buckets on the three 6,000 kVA. units. The other set is reamed ready for fitting to No. 2 turbine.

Generator-running times were as follows:-

	Generator No.		Time on Load.		Time Idle.		Time under Repair.		
			Hours.	Percentage.	Hours.	Percentage.	Not in Demand (Hours).	In Demand (Hours).	Percentage Availability for Service.
1 2 3 4 5			8,274 8,304 8,168 8,369 8,363	$94 \cdot 2$ $94 \cdot 5$ $93 \cdot 0$ $95 \cdot 3$ $95 \cdot 2$	475 434 396 404 413	5·4 4·9 4·5 4·6 4·7	35 46 220 11 8		99.6 99.4 97.5 99.9

A contract has been let for the supply of replacement gates for the by-pass tunnel of No. 1 dam. Negotiations are in hand for a contract for similar gates for No. 2 dam.