Appendix P.—continued.

RETURN of Wrecks on which Inquiries have been held, &c.—continued.

	Remarks.		Total loss.	ပိ	ceruncate to be cancelled. Mate and one hand drowned.			This vessel was got off with but little damage.		Became a total wreck.		Sold. The new owners have recovered and repaired her.			E	repairing ner. Became a total wreck.	Became a total wreck.	Total wreck. Master acted with judgment.
N of Wrecks on which Inquiries have been held, &c.—continued.	Finding of Court of Inquiry.		Master did not make sufficient allowance	Bad management and error of judgment	on part of master. No blame attaches to the master. Wreck caused by neglect or incompetence	or master or both The master appears to have misjudged his distance from the shore. He ap-	pears to have done what he could to save the vessel after the accident. Wreck accidental: no one to blame.	The fug took the ground. The master of the "Ocean Wave" then tried to sail in, but the current was too strong, and	she also was stranded The master thought he was past this	Master of tug blamed for keeping to much to the northward. Master of "Flizabeth," blamed forment of managed	in trying to save vessel and cargo after stranding	Master not specially blamed, but it was considered that he had undertaken too	neavy a tow under an one circumstances. The captain is blamed for the first accident, for "too much frailty in giving in to the ownion of the mate and seamen	as to what land was seen." The signal- man at Barrel Beacon is blamed for the final catastrophe, for "not making out	and repeating signals" of distress. The master acted properly in beaching the vessel to save life, as she was leaking badly	Accident caused by want of proper look-	Cable parted. Master blameless	Cable parted. Master blameless
	Place where Accident occurred.		Mitiera Reef, South-	Buller Bar	Urinui River 4 miles N. of Mana-	watu Near East Cape	Okarita Bar	North Spit, Hokitika	Rurima Reef, near	Whale Island North Spit, Hokitika		Sumner Bar	Struck the Beach, near Kapiti; after- wards became a	wreck in Fitzroy Bay, entrance to Wellington Har-	bour On Beach, north of the Grey River	Rangitoto Reef	Mouth of Grey River	Mouth of Grey River Cable parted.
	Wind.	Force.	Moderate	Fine weather	Fine weather Strong	Ē	Fine weather	Fine weather	Moderate	Moderate weather		Fine weather	Fresh		Неаvу вса	Moderate	Moderate weather;	heavy sea Strong
		Direction.	:	:		:	;	: :	:	:		÷	N.W.		:	:	. :	Westerly
	to ted.	mu V SeviaI	:	:	:∞	:		: :	:	:		:	:		:	:	:	:
	Nature of Casualty.		Stranded	Total wreck	Total wreck Ditto	Ditto		Stranded	Total wreck	Stranded		Ditto	Total wreck		Ran on shore	Stranded	Ditto	Ditto
RETURN	Nature of Cargo.		General	Coals	Ballast Coals and	maize Oil	General	Ditto	Ditto	Ditto		Ditto	Coals		General	Firewood	General	Ditto
	Number of Passengers.		:	:	: :	:		: :	63	:		:	:		40	63	:	:
	Register Tonnage.		70	:	42	ಣ		000	4	<i>y</i> 0		:	3 11		13	23		- K
			34	192	19	29		117	25	113		46	346	****	68	14	43	28
	Rig.		Cutter	Brig	Cutter Schooner	Cutter		Ditto	Ditto	Ditto		8. 8.	Barque	,,	P.S.	Schooner	Ditto	Ditto
	Name of Vessel; also, Age and Class when known.		Hercules, 2 years		zə years Lizzie, 9 years Manukau	Lady Wynyard, 2 years		Ocean Wave, 2	Hope, 11½ years	Elizabeth, 18 years		Gazelle	Affiance, 17 years		Charles Edward, 3 years old		Flying Cloud, 7	
	Date	Casualty.	1867 Sept. 2	ž ž	0ct. 4	"		181	, 31	Nov. 2		esi	; ,	·	ε	7		9