

TABLE L.—APPENDIX I.

STATEMENT showing QUANTITY and STATE of ROLLING-STOCK on the MIDDLE ISLAND RAILWAYS on 30th June, 1878.

LOCOMOTIVES.

Description.	8-in. cyl., 4 wheels, coupled, 8 tons.	9-in. cyl., Fairlie, 8 wheels, coupled, 23 tons.	9½-in. cyl., 4 wheels, coupled, 12 tons.	9½-in. cyl., 4 wheels, coupled, Bissel truck, 12 tons.	10-in. cyl., Fairlie, 8 wheels, coupled.	10½-in. cyl., 6 wheels, coupled, 17 tons.	10½-in. cyl., 4 wheels, coupled; with 4-wheel bogie.	Fell engines, 14-in. cyl. outside, 10-in. cyl. inside, 4 wheels, coupled.	14-in. cyl., 6 wheels, coupled, Bissel bogie, 25 tons, 6-wheel tender.	12-in. cyl., American engines, 4 wheels, coupled, 2 Bissel bogies, 8-wheel tender.	10½-cyl., 4 wheels, coupled, with Widmark's radial box on leading axle.	13-in. cyl., 6 wheels, coupled, tank engines, 28 tons.	10½-in. cyl., Fairlie, 8 wheels, coupled, 25 tons.	10½-in. cyl., 6 wheels, coupled, tank engine, radial box on leading axle.	8-in. cyl., 6 wheels, coupled, New Zealand-built, 12 tons.	8-in. cyl., 4 wheels, coupled, 10 tons.	Total Number.
	Class A.	Class B.	Class C.	Class D.	Class E.	Class F.	Class G.	Class H.	Class J.	Class K.	Class L.	Class M.	Class N.	Class O.	Class P.	Class S.	
CHRISTCHURCH.																	
In good order ...	11	...	1	1	...	4	4	...	6	2	1	2	...	3	2	1	...
Undergoing heavy repairs	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...
Undergoing light repairs	1	...	...	...	...	2	...	...	...	...	...	...	...	...	...	...	...
In course of erection	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...
Total ...	12	...	1	1	...	6	4	...	6	2	1	2	...	3	2	1	41
DUNEDIN.																	
In good order ...	...	1	...	...	5	5	...	...	...	...	...	...	...	7	...	...	...
Undergoing heavy repairs	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...
Undergoing light repairs	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...
In course of erection	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...
Total ...	...	1	...	...	5	5	...	...	...	...	...	...	...	7	...	...	18
INVERCARGILL.																	
In good order ...	1	...	1	...	...	4	...	...	...	...	...	2	...	6	...	...	...
Undergoing heavy repairs	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...
Undergoing light repairs	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...
In course of erection	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...
Total ...	1	...	1	...	...	4	...	...	...	...	...	2	...	6	...	...	14
GREYMOUTH.																	
In good order ...	...	...	2	...	...	...	...	...	...	...	...	...	...	...	...	...	...
Undergoing heavy repairs	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...
Undergoing light repairs	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...
In course of erection	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...
Total ...	...	...	2	...	...	...	...	...	...	...	...	...	...	...	...	...	2
WESTPORT.																	
In good order ...	...	...	3	...	...	...	...	...	...	...	...	...	...	...	...	...	...
Undergoing heavy repairs	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...
Undergoing light repairs	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...
In course of erection	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...
Total ...	...	...	3	...	...	...	...	...	...	...	...	...	...	...	...	...	3
NELSON.																	
In good order ...	...	...	...	2	...	...	...	...	...	...	...	...	...	...	...	...	...
Undergoing heavy repairs	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...
Undergoing light repairs	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...
In course of erection	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...
Total ...	...	...	...	2	...	...	...	...	...	...	...	...	...	...	...	...	2
PICTON.																	
In good order ...	...	...	2	...	...	...	...	...	...	...	...	...	...	...	...	...	...
Undergoing heavy repairs	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...
Undergoing light repairs	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...
In course of erection	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...
Total ...	...	...	2	...	...	...	...	...	...	...	...	...	...	...	...	...	2
Grand total ...	13	1	9	3	5	15	4	...	6	2	1	4	...	16	2	1	82