GOLD-DREDGING, WORKING DREDGES INSPECTED.

		Direction	LANGUAGE INSTITUTION	
Name of Dredge.	Owners.	Dredgemaster.	Remarks.	Date of Visit.
CLUTHA RIVER.	Lioness Gold-dredging Company	J. Templeton	Erecting machinery	15/7/01. 18/9/01.
Paul's Béach, below Beamont.	Paul's Beach Gold dredging Company	William McLelland J. Herbert		16/7/01.
Golden Reward, below Beaumont			Two boat hooks missing	18/10/01. 23/8/01.
Golden Gravel, Beaumont	pany Golden Gravel Gold-dredging Com- pany	T. Barnes	Shifting dredge to lower claim; appliances in fair order Erecting machinery Dredge and life-saving appliances in good order	19/10/01. 28/5/01. 17/7/01.
Golden Run, Miller's Flat	Golden Run Gold-dredging Company	P. Brandt	Dredge and appliances in good order	19/10/01. 29/5/01.
Pringle's, Miller's Flat	Pringle and party	J. Pringle	Hand-rail and 100t-plank required as approach to elevator; otherwise in good order Dredge and appliances in fair order	$\frac{18/10/01}{29/5/01}$.
Golden Gate, Miller's Flat	Golden Gate Gold-dredging Company	D. Ballantyne	Stopped by flood; appliances in good order	18/10/01. 29/5/01.
Otago, Miller's Flat	Otago Gold-dredging Company	R. Williamson	Shiring to bottom of claim; dredge and appliances in good order	$\frac{18/10/01}{30/5/01}$.
Golden Treasure, Miller's Flat	Golden Treasure Gold-dredging Com-	T. Cornish	Light-lines and boat-hooks required; life-buoys need repairing	$\frac{17}{10}/01$. $\frac{30}{5}/01$.
Majestic, above Miller's Flat	pany Majestic Gold-dredging Company	W. Williamson	Dredge and life-saving appliances in good order Boat-hooks and light-lines require renewal	$\frac{17/10/01}{30/5/01}$.
Golden Bed, Ettrick	Golden Bed Gold-dredging Company	A. Maitland	Dredge and life-saving appliances in good order Boat-hooks and light-lines required on the dredge; also a buoy and boat-hook in the boat Life-saving apparatus out of order. The company was notified to provide a suitable boat in	17/10/01. $30/5/01$. $22/8/01$.
Bttrick, Ettrick	Ettrick Gold-dredging Company	T. Thompson	place of the second boat, which was too small Erecting machinery Four life-buoys, with 15 in. inside measurement, were too small. I pointed this out to the	18/7/01. $14/12/01.$
Excelsior, Ettrick	Excelsior Gold-dredging Company	J. Wallace	dredgemaster, and the buoys were returned, and replaced with proper ones Erecting machinery Soreen and elevator driving gear requires to be guarded; bar across coal-door needed; other-	18/7/01. 12/10/01.
Gibbs's Beach, Moa Flat	Gibbs's Beach Gold-dredging Com-	T. Kitto	Wise appliances in good order Ready to start	30/5/01.
Moa Flat, Moa Flat	pany Mos Flat Gold-dredging Company	T. Thompson	Dredge and appliances in good order	18/7/01. 30/5/01.
Gold Queen, Dumbarton Rock Gold King, Dumbarton Rock	Gold Queen Gold dredging Company Gold King Gold dredging Company	C. Olsen G. Magnus	New boat provided; dredge closed down Dredge and life-saving appliances in good order Ready to start. Some of the after driving-gear requires to be guarded; also main and pump	22/8/01. 18/7/01. 16/10/01.
Endeavour, Dumbarton Rock	Endeavour Gold-dredging Company	A. Rennie	uriving-tens to be tended; inactural to be cut att for access bening the pump. The said pump belting requires to be fenced off. The required connect the coeledor.	22/8/01.
Teviot, Roxburgh	Teviot Gold-dredging Company	_	Regulations not posted; only one boat; no life-saving apparatus; new dredge just starting Life-saving appliances now in good order	31/5/01. 31/5/01. 21/8/01.
		P. McVicar	Visited dredge in connection with fatal accident on 23rd September, 1901, and found dredge and life-saving appliances in good order. A. McCormack, fireman, was killed on 23rd September, 1901, caught by elevator driving-shaft while ciling, machinery being in motion	25/9/01.