No. 2.—RETURN of DEFECTS—continued.

Description of Defec	cts.		!	Dangerous.	Defective in Lesser Degree.	Total
Manhole-door studs bad				• • •	4	4
Manhole-openings in shell wasted .		•••		•••	5	5
Mudhole-doors bad 28907.				•••	38	38
Mudhole-door studs bad 🐬 .				•••	14	14
Mud-drums grooved and corroded .	•••	•••		•••	4	4
Nine tubes bad			,		1	1
One hundred and thirty-seven scre- bad	wed sta	ays in fire	ebox	1		1
One longitudinal stay bad	••		• • •	• • •	5	5
N	••	•••	•••	•••	5	2 5
Non-state tooks by 3	••	•••	• • • •	•••	1	1
Nun duha had				•••	11	. 11
Patches defective				•••	12	12
		•••			6	6
				•••	22	. 22
Rivets in manhole compensating-ring		•••			2	2
Rivets in manhole-door bad		***			3	3
Rivets in tube-plate defective					2	2
addle-plate wasted				•••	1	1
screwed stays pitted slightly .	••			•••	2	2
leams leaking		• • •		•••	1	1
even rivets in front tube-plate bad	••	•••	•••	•••	2	2
leven rivets in firebox bad leven screwed stays in firebox bad	• •	• • •		•••	$\frac{1}{1}$	1 1
		•••	••••	•••	2	$\frac{1}{2}$
even tubes bad eventy screwed stays in firebox bad		•••	•••	 1	4	i
several rivets in shell bad		•••		•	ì	1
shell wasted around skirting					6	6
hell wasted at back and circumfered	ntial se		}	•••	i	ĭ
hell wasted at bottom inside				4	17	$2\overline{1}$
shell wasted at circumferential seam	าธ			1	4	5
hell wasted at crown of boiler				•••	3	3
hell wasted at crown round uptake		• • •		•••	1	1
hell wasted at foundation-ring				•••	2	2
	••	• • •	• • •		1	1
hell wasted at the landings			• • •	•••	2	$\frac{2}{70}$
hell wasted at manhole-openings	• •	• • •	•••		72	72
shell wasted at mudhole-openings shell wasted at top circumferential s		• • •	•••	•••	3 1	3 1
hell wasted at water-line	веншв	•••		•••	2	2
1 -11	• •	•••	•••	•••	2	$\frac{2}{2}$
hell wasted externally	••	•••	[•••	3	3
shell wasted where blow-off cocks jo	ointed o	n boiler	•••		4	4
hell wasted where check-valve ches				•••	3	$\bar{3}$
shell wasted where feed-pump chest				•••	72 ~	2
hell wasted where safety-valve ches	st jointe	ed to boile	er		4	4
(: 3 - a of Guaham Ahim					6	6
ix rivets in shell bad					2	2
	••				1	1
ix tubes bad	••				$\frac{2}{1}$	2
ixteen screwed stays in firebox bad		• • •	•••		1	1
ixteen tubes bad	 Ov	•••	•••	i	1	1 1
ixty-five screwed stays bad in firebo	UX	•••		1	ï	1
tay-nuts on front tube-plate bad team-domes wasted	••	•••		•••	3	3
team-drum wasted				• •••	1	1
team space-stays wasted	••			•••	2	$\hat{f 2}$
	••			•••	4	4
en tubes bad				•••	6	6
hree rivets in manhole-door bad		• • •			1	1
hree screwed stays in firebox bad		• • •		•••	3	3
hree tubes bad		•••			4	4
hirty-two screwed stays bad				1	•••	1
hroat-plates thin		,	、…↓	•••	3	3
op row of screwed stays at back en	d of fir	ebox had	l	•••	1	1
op row of tubes badly fitted	••	• • •	• •		1	1 5
			1	1	4	Λ.
op tube-plates thin 'ubes bad	••	•••			89	89