

No. 3.—RETURN of NOTICES given to REPAIR BOILERS—*continued*.

Number.	Type.	Description of Repairs.
3	Locomotive	... Patches fitted on throat-plate.
1	"	... Patches renewed.
1	"	... Retubed.
1	"	... Retubed, and new front tube-plate fitted.
1	"	... Seams caulked, stays rejointed, and sight-holes cut.
1	"	... Several rivets renewed in foundation-ring.
1	"	... Several stay-nuts on firebox-crown renewed.
1	"	... Several tubes renewed.
1	"	... Three patches fitted in firebox.
1	"	... Two sight-holes bored in firebox, and plugs fitted.
1	Manure-dryer	... Longitudinal seams caulked.
1	Marine ...	... Patches fitted on shell under check-valve and blow-down cock, also leaky seams pared and caulked.
1	"	... Patches in combustion-chamber extended.
1	"	... Retubed.
1	Multitubular	... Compensating-ring round manhole-opening riveted.
14	"	... Brickwork repaired.
1	"	... Bulge cut out of bottom of shell, and patch riveted on.
1	"	... Bulge cut out of bottom of shell, and new mud-leg fitted.
4	"	... Circumferential seams on bottom recaulked.
2	"	... Compensating-rings fitted round manhole-openings.
4	"	... Compensating-rings fitted round mudhole-openings.
1	"	... Compensating-rings fitted round mudhole-openings, and new doors fitted.
1	"	... Compensating-ring fitted round mudhole-opening, and new dog for door.
1	"	... Compensating-ring fitted round mudhole-opening, new door fitted, and five new rivets put in shell.
1	"	... Cracked portion cut out of bottom of shell, and patch 22 in. long riveted on.
1	"	... Defective portion of plate cut out of bottom of shell, and patch 48 in. by 18 in. riveted on.
1	"	... Eighteen new tubes fitted.
1	"	... Five new rivets put in gusset stay.
1	"	... Five new stay-tubes fitted.
1	"	... Five new tubes fitted.
1	"	... Four new stay-tubes fitted.
1	"	... Four rivets renewed in bottom circumferential seam.
1	"	... Fourteen new tubes fitted.
2	"	... Front tube-plates patched.
1	"	... Laminated portion of plate cut out of bottom of shell, and riveted patch fitted.
4	"	... Manhole-doors repaired.
3	"	... Manhole-door spigots renewed.
1	"	... Manhole-door spigot riveted.
1	"	... Manhole-opening dressed out, new manhole and new mudhole doors fitted.
1	"	... Mud-drum riveted to shell.
1	"	... Mudhole-doors repaired.
2	"	... New bottom-plates put in shell.
1	"	... New flanged plate fitted and riveted to the bottom of steam-dome.
7	"	... New manhole-doors fitted.
1	"	... New manhole-door fitted and compensating-ring round manhole-opening riveted.
1	"	... New manhole-door fitted and compensating-ring round mudhole fitted.
2	"	... New spigots riveted on manhole-doors.
1	"	... New spigot riveted on manhole-door, and compensating-ring fitted to mudhole-opening.
3	"	... New studs fitted in mud-doors.
1	"	... Nine rivets in front tube-plate renewed.
6	"	... One new longitudinal stay put in boiler.
2	"	... One new tube fitted.
1	"	... Patch fitted at back end and compensating-ring to mudhole-opening.
1	"	... Patch fitted on back tube-plate.
1	"	... Patch fitted on bottom of shell under seams.
1	"	... Patch fitted on bottom of shell 48 in. by 18 in., and thirty-eight new tubes fitted.