

RETURN showing the NOTICES to MARINERS relating to Matters within the Dominion issued by the Marine Department during the Year ended 31st March, 1911.

Port or Place.	Subject of Notice.
Auckland Harbour	Removal of rocks, Rangitoto Channel.
"	Removal of Freeman's Bay Dolphin and Kaipara Shoal.
"	Light-vessel.
"	Dredging channel, Shoal Bay.
"	New light on Railway Wharf.
"	Bean Rock light.
"	Protected anchorages for yachts.
"	Wharf lights.
"	Light on O'Neill's Point Wharf.
"	Magnetic bearings of leading-lights on O'Neill's Point Wharf.
"	Light on Orakei Wharf.
"	Pile-driver near No. 4 Jetty.
"	Protected anchorages for yachts.
"	Kaipara Shoal.
"	Signals revised.
Bluff Harbour	Lights established.
Cape Maria van Diemen	Characteristics of light changed during repairs.
"	Characteristics resumed.
"	Use of revolving light resumed.
Dusky Sound	Rock off Indian Island.
"	Dangerous rock south-west of Parrot Island.
"	Dangerous rock south-west of Parrot Island (further notice).
Gisborne	Dredging operations.
Godley Head Light	Arc of visibility.
Golden Bay	Terakohe Wharf.
Great Barrier Island	Beacons erected at Whangaparapara Heads.
"	Light on beacons at Whangaparapara Heads.
Greymouth Harbour	Night signalling by Morse system.
Hokianga	Change in channels.
"	Soundings in channels.
"	Soundings in channels (further notice).
Kaipara Harbour	Change of channel and buoys in Wairoa River.
"	Alteration of buoys in Wairoa River.
"	Entrance to harbour.
Kawhia	Alteration of bar and change of beacons.
"	Change of leading-beacons.
Lyttelton Harbour	Dredging operations.
Manukau Harbour	Beacon re-erected.
Napier	Glasgow Wharf light.
Nelson	Wreck of s.s. "Koi."
"	Removal of wreck of s.s. "Koi."
"	Leading-marks for approach.
"	New buoys and shoaling.
"	Shoaling of harbour.
"	Dredging operations.
"	Dredging operations (further notice).
New Plymouth	Dredging at entrance.
"	Position of dredge changed.
New Zealand coast	Corrections to be made in "New Zealand Pilot," 8th Edition, 1908.
"	Four-fathom Shoal off Cheviot coast.
"	"New Zealand Nautical Almanac," and "Tide Tables," and "Supplement to the New Zealand Pilot," 8th Edition, 1908.
"	Three-fathom Shoal off Cheviot coast.
"	Bushett Shoal off Cheviot coast.
"	"New Zealand Nautical Almanac," <i>errata</i> .
"	Three Kings incorrectly charted.
Oamaru	Dredging operations.
"	Breakwater light.
Otago	Main channel, Harrington Point to Port Chalmers: Change in colour and new lights established.
"	Alteration in position of beacons.
"	Main channel, Harrington Point to Port Chalmers: New lights established.
"	Exhibition of light on Goat Island.
"	Port Chalmers signals.
"	Removal of buoy south of Harrington Point.
"	Beacons in lower harbour.
Poverty Bay	Tuahine Lighthouse removed.
Queen Charlotte Sound	Change in light on Jackson's Head beacon.
"	Characteristic of light on Jackson's Head changed temporarily.
"	Characteristic of light resumed.
"	Light on Dieffenbach Point.
Stewart Island	Shoal off Paterson's Inlet.
"	Reported rocks off Stewart Island.
"	Rock off South-west Cape.
Sumner Estuary	Sandbank in.
Tokomaru Bay	Buoys placed in.
"	Leading-beacons erected.
Wairau River	Black buoy at mouth of.
Waitara Harbour	Night signalling by Morse system.
Wanganui River	New mole and light at entrance.
Wellington Harbour	Lights at seaward end of Clyde Quay Wharf.
"	Light on Petone Wharf.
"	Light on seaward end of Wellington Harbour Board City wharves.
"	Temporary electric arc lights on Dorset Point.
Whangarei Harbour	Change in character of harbour light.