

- 17/5/27 Wireman received burns whilst setting conduit for new mains (Taranaki Power Board).
 - 9/6/27 Lineman killed due to shock and fall from pole (Wellington).
 - 17/6/27 Operator received shock and burns due to handling 6,600-volt fuse through failure to use protective apparatus provided (Taranaki Power Board).
 - 25/6/27 Boy playing on roof of cow-shed received burns due to contact with overhead lines (Thames Valley Power Board).
 - 1/7/27 Horse electrocuted in Hamilton by accidental contact with 3,000-volt line.
 - 13/7/27 Lineman severely injured by fall from pole (Hastings).
 - 14/7/27 Operator severely burnt while operating 3,300-volt air-break switch, due to defective insulator (Manawatu-Oroua).
 - 20/8/27 Child at Tikorea received shock from live fence-wire.
 - 23/9/27 Engineer injured by fall from pole due to electric shock (Havelock North).
-