RETURN OF WRECKS AND CASUALITES TO SHIPPING REPORTED TO THE MARINE DEPARTMENT FROM 1ST APRIL, 1935, TO 31ST MARCH, 1936-continued.

nber of Passen-	Register Tonnage.	Number of Passen-	Number of Passen-	-u	(	Na	Nature of	Number of Lives lost.	Place where Casualty occurred.		Wind.	Finding of Court of Inquiry.	Name of Master.
	Crew gers.	Crew gers.	Crew gers.		Cargo.		Casualty.	TOSE.		Direction.	Force.		
1985. July_13 Binta, m.v.; 7 years Schooner 3,421 83 Xii 6,170 tons gasoline, kerosene, &c.	Schooner 3,421 33 Xii 6,170 tons gasoline, kerosene, &c.	3,421 33 Xil 6,170 tons gasoline, kero- sene, &c.	Xii 6,170 tons gasoline, kero- sene, &c.	6,170 tons gasoline, kerosene, &c.			Compressor of main engine damaged	Nill	Off Castle Point	W.N.W.	ಹಿ	A heavy bang was heard in the engine- room, and, on investigation, a bolt of the cross-rim had broken and fallen, causing damage to the compressor,	A. W. Norvalls.
Makura, s.s.; 27 years Schooner 4,920 134 140 2,000 tons general	Schooner 4,920 134 140 2,000 tons general	4,920 134 140 2,000 tons general	140 2,000 tons general	2,000 tons general			Port anchor and 50 fathoms cable lost	S NII	Rarotonga	e <b>i</b>	2-9	which was repaired at Wellington Whilst at anchor vessel encountered strong casterly whot, causing her to drag and	D. Macdonald.
Huntingdon, s.s.; 17 years Schooner 6,881 56 Nil Nil	Schooner 6,881 56 Nil Nil	6,881 56 Nil Nil	Xii Xii	Ni	:		Main steam-pipe fractured	Nil	Lat. 47° 00′ S.; Long. 153° 20′ E.	S.W.	S	A small fracture was discovered in the starboard forward boiler's main steam-	H. E. Reilly.
(Lancia, o.e.v.; 15 years Cutter 6 1 1 Nil	Cutter 6 1 1 Nil	6 1 1 Nil	1 Nil	:: :: IIX	:							pipe, the cause of which was unknown The "Lancia" was towing the barge "Rover," and, on passing between some yachts at anchor, the tow-rope caught	E. C. Lannam.
							Collision	E .	Auckland Harbour	N.W.	æ	the "Glady" and dragged her against the barge, splitting the Jib-boom of the "Glady" for a distance of 5 ft.	
Motu, m.v.; 15 years Schooner 109 10 Nii 50 tons general	Schooner 109 10 Nii	iiv 0i 00i .	Nii		50 tons general	:	Damaged starboard propeller	IIN .	Awanui River	N.W.	6	Whilst the vessel was proceeding down the river, which was in flood, the starboard propeller fouled an unseen sunken log and was damagned.	F. G. Shirley.
Breeze, m.v.; 2 years 316 15 Nil 200 tons general	316 15 Nil	15 Nil	NII		200 tons general							The Court found that the collision was due to the "Bessie" crossing ahead of the "Breeze" owing to lack of knowledge of regulations by the person steering the "Bessie," and recommended that a copy "Bessie," and recommended that a copy	Robert T. Stewart.
							Colliston	NII	Off Paeroa (near Timaru)	•	Calm	or regardons be supprent need to danger to each licensee on registration of fishing- boat, and that presons in charge of launches be required to have working knowledge of regulations, and ordered the owner of "Besse" to pay £17 12s. 6d.	
7 8 Nil	7 8 Nil	3 Nil	IEN		Cases of petrol and fishing gear						_	Current to cooks community	Ronald F. Latimer.
Fordsdale, s.s.; 11 years Schooner 5,647 65 1 7,500 tons general	Schooner 5,647 65 1	5,647 65 1	m		7,500 tons general	:	Damaged boats, ventila- tors, &c.	- XII	Lat. 35° 24′ S.; Long. 179° 20′ E.	w.	o,	The vessel shipped a heavy sea on the star- board side, damaging weather boats,	Douglas Christie.
Natone, s.s.; 35 years Cutter 50 4 Nil Nil	Cutter 50 4 Nil Nil	4 Nii Nii	Nil Nil ::	Nil ::	:		Damaged hull, &c.	Nil	Wellington Patent Slip	:	Calm	The vessel was on the cradle, and, on being haude up on the slip, a chock failed to hold, resulting in vessel being thrown on the side being thrown on the side breaking several planks and the side breaking several planks and the side of the slice.	H. W. Hargraves.
Huanui, m.v.; 25 years   Ketch 56 7 Nil 120 tons coal	Ketch 56 7 Nil 120 tons coal	56 7 Nil 120 tons coal	Nil 120 tons coal	120 tons coal	:		Stranded	IN	Manawatu River	:	Calm	The vessel was drawing furth, and as there was only 6 ft. 6 in. of water in river-channel, she stranded on a sandbank, and other being right-channel.	T. C. Thomsen.
Fairburn, m.v.; 29 years   Schooner 60 6 Nil 42,000 ft. timber	Schooner 60 6 Nil 42,000 ft. timber	60 6 Nil 42,000 ft. timber	Nil 42,000 ft. timber	42,000 ft. timber			Broken crank-shaft	Nil	Cook Strait	σi	4-5	Man, are to being gigheren, was fendaded When vessel was one mile east of Jackson Head the engineer reported that crankshaft of starboard engine was broken, vessel proceeded to Wellington to have	T. C. Sawyers.
9	Ketch 42 6 Nil 100 tons cement	42 6 Nil 100 tons cement	Nil 100 tons cement	100 tons cement			Port propeller lost	NII	Auckland Harbour	:	Calm	a new state installed was going to anchor in Shoal Bay the port propeller was lost, but no damage was sustained by the bussel on how aways.	W. E. Aspden.
Echo, m.v.; 30 years Schooner 99 10 Nil Approximately 56 tons	Schooner 99 10 Nil Approximately 56 general	99 10 Nil Approximately 56 general	Nil Approximately 56 general	Approximately 56 general	56		Shackle carried away and damaged sail		Cook Strait	N.W.	∞ .	During strong northerly gale and rough sea peak-halyard shackle carried away, the peak of the galf penetrating the sall, necessitating vessel being towed to Wellington, where a new sail was placed on board	P. A. Miles.