Charles Quentin Pope.	Sanford S. Miner. James Brother. ton.			William S <b>mith</b> .
ness on the master's part. His certificate suspended for six months. Second mate cautioned that he should always ask for chart, &c. Chief engineer neither entered in his registor the damage done to vessel, nor reported striking to the inspecting engineer. Chief mate, Smith, failed to enter in log record of what occurred on various occasions, and made irregular additions to it. Master to pay costs of inquiry Shaft broke while vessel on way from Wanganui to Wellington, and propeller dropped of	One of the ship's boats, with a crew of six men, blown off Campbell Island and lost Charge of inebriety against master not supported by evidence. Master fell asleep on bridge. This was caused by overwork on day of vessel's departure from Auckland, and by exhaustion from want of sleep and	pain from neuralgia. Being in that state he should not have trusted to his own powers of watchfulness, but should have kept some one with him on the bridge. The order to steer by the light was an improper order to give. A course by compass should have been given, and a man stationed between the forecastle-head and the bridge to repeat warnings or orders, more especially as the wind was blowing S.S.E., nearly from aft, forward. Master's certificate suspended	for three years. Chief mate, Thomas Owen, neglected his duty in not keeping a look-out while on deek, as it was an important, if not the most important, part of his general supervision of the work on deck to have assisted the master in this respect. His certificate suspended for six months. The second officer was entirely free from blame. The quartermaster, in steering for the light for so long a period as twenty minutes without calling attention of master, showed a neglect of duty amounting to little short of	wilful misconduct, and is deserving of the gravest censure. O'Halloran, the look-out, was guilty of neglect of duty. Master ordered to pay three-fourths of cost of inquiry, and chief officer one-fourth Casualty caused by vessel taking a sheer when nearing the inner bar, and, it blowing strong from the westward, and there being a fresh in the river, she would not answer her helm, and so was driven on to the Inner North Spit
Light	Strong gale Light			Strong
තු ප්	W.S.W.			B
Three miles S. of Mana Island, Oook Strait	Campbell Island East end of Tiri Tiri, Hauraki Gulf			Inner North Spit, Buller River
:	φ :			:
Loss of propeller	County Loss of Life only Stranded; total loss			Stranded; slight damage
Produce	Nil, seal- ing voyage General			Coal
:	: <del>-</del>			:
9	15 61			16
	109			788
Schooner	* *			Sobooner
Tui, s.s., 9 years	Sarah W. Hunt Triumph, s.s., 3 years, 100 A1 Lloyd's		C.	Kawatiri, s.s., 1 year
Nov. 27	29		a de la companya de l	Dec. 3