Waikare River - Waikoau River: Minor improvements were undertaken and 17,000 cubic yards of metal spread over the full length of this section of 14\frac{3}{4} miles. The whole length was primed, 141 miles were sealed with road oil and 1 mile was sealed

Tangoio Lagoon Bridge - Whirinaki: This section of 1 mile 68 chains was metalled,

primed, and sealed.

Esk River Bridge Approaches and Esk Overbridge Approaches: These two approaches form a continuous length of 1 mile 45 chains and the whole was primed and sealed with road oil.

No. 22 State Highway, Taupo-Napier.—Metalling, priming, and sealing were completed over two gravelled sections totalling 2 miles 65 chains, thus providing a continuous sealed surface to Mistletoe Hill, approximately 25 miles from Napier. These two sections were between Dillon's Hill and Munn's Bridge.

Maintenance Sealing (23 miles 44 chains)

The following sections received maintenance-seal treatment, proceeded in some cases by extensive metalling :-

No. 25 State Highway, Gisborne-Napier via Hangaroa:

				M. ch.	
Frasertown-Wairoa				1 24	M.C. 3 and pea gravel.
Wairoa Borough	• •				M.C. 3 and grit.
Whirinaki South	••		• •	0.40	M.C. 3 and pea gravel.
William Society	••	• •		0 10	in.e. o and pea graver.
No. 813 Main Highway, Gisborne-Wairoa via Morere:-					
•				M. ch.	
Wairoa Borough				$0.19\frac{1}{2}$	M.C. 3 and grit.
No. 30 State Highway, I	Janier - P	almareta	n Nor	rth •	
110. 00 State Highway, 1	apiei – i	win o r sw	76 1101		
D-1-: D-1-: IB. A4-				M. ch.	No. 1 tow and man amount
Paki Paki – Te Aute	• •	• •	• •	0 60	No. 1 tar and pea gravel.
Takapau Plains	• •	• •	• •	11 40	M.C. 3, 9 miles; No. 1 tar,
36				2.00	$2\frac{1}{2}$ miles.
Mangatewai-iti Hill	• •	• •		2 20	M.C. 3 and chips.
Maharahara					Road oil and chips.
Matahiwi South					Road oil and chips.
Daveys Road				0.26	No. 1 tar and chips.
Mangapapa Bridge a	pproaches			0 14	Road oil and chips.
Mangamanaia Overb	ridge			0 6	Road oil and chips.
No. 341 Main Highway,	Woodvill	e-Tamai	ki :		
1.0. 011 12 ant 11 tg. 11 ag,	,, 00,0000			M. ch.	
Dannarinta Countre				.0 66	Plant mix.
Dannevirke County	• •	• •	•		riant inix.
37	77 7	n 1 '	7) 7 .	M. ch.	D () 1
No. 567 Main Highway,	Farndon	-Paki.	Pakr	2 22	Reconstruct, metal, and
				36 1	reseal (tar).
37 405 34 1. 71: 7	777 . 7 . 7	70.7	y•	M. ch.	NT - 1 / 1 -1
No. 495 Main Highway,	w aroniki	–Pakow.	naı	0 13	No. 1 tar and chips.

over 192 chains of the Woodville County section of the Woodville-Masterton State Highway, and this has been treated with No. 1 tar and grit.

In addition to the above, extensive reconstruction and metalling was completed

No. 570 Main Highway, McLean Street North. — Twenty-seven chains were reconstructed and metalled.