

Name of Dredge.	Owners.	Dredgemanster.	Remarks.	Dates of Visits.
<i>CLUTHA RIVER—continued.</i> <i>Alexandra—continued.</i>				
Earnsleugh No. 1 ..	Earnsleugh Gold-dredging Company	J. Fouhy ..	Life-saving appliances not on board. This was attended to at once; runner required for boat-line	3/6/01.
Earnsleugh No. 2 ..	Earnsleugh Gold-dredging Company	" ..	One life-buoy requires recovering; otherwise appliances in good order	9/10/01.
Chicago ..	Chicago Gold-dredging Company	J. McDonald	Undergoing repairs ..	3/6/01.
			Dredge and appliances in good order ..	9/10/01.
			Life-saving appliances require renewal. While running a head-line the line fouled, the boat swamped, and the crew (five men) were thrown into the river. Having life-belts on and boots unlaced, in case of emergency, all the men got out safely. Date of accident, 20th April, 1901.	6/6/01.
Glasgow ..	Sandy Point Gold-dredging Company	W. Hansen	Well-gangway required; engine to be railed in	9/10/01.
			Railing required forward ..	3/6/01.
Perseverance No. 1 ..	Perseverance Gold-dredging Company	S. Cameron	Set-screws on collar on screen driving-shaft to be guarded	9/10/01.
			Light-lines and boat-hooks required ..	3/6/01.
Perseverance No. 2 ..	Perseverance Gold-dredging Company	"	Dredge and appliances in good order ..	17/8/01.
			Undergoing extensive overhaul ..	17/8/01.
<i>Below Clyde.</i>				
Dunstan Lead ..	Dunstan Lead Gold-dredging Company	D. Brigans	Getting ready to start ..	23/7/01.
			Sleeve required on engine-shaft, also on winch-engine shaft; guard required round winch engine	23/9/01.
Matau ..	Matau Gold-dredging Company	H. Sanders	Regulations to be posted in a more conspicuous place; dredge and appliances in good order	22/7/01.
Unity ..	Unity Gold-dredging Company	T. Barry ..	Light-lines not in place; fencing required below tables; also guard on feed-pump, and ladder up the gantry	22/7/01.
<i>At Clyde.</i>				
Vincent ..	Vincent Gold-dredging Company	J. Hewitt ..	Repairing; life-saving appliances not yet up to the mark	17/8/01.
Vincent Extended ..	Vincent Extended Gold-dredging Company	J. von Haast	One life-buoy, 100 ft. light-line, and one boat-hook required	23/7/01.
			Dredge and life-saving appliances in first-class order ..	24/7/01.
<i>Clyde—Cromwell Gorge.</i>				
Cairnmuir ..	Cairnmuir Gold-dredging Company	D. McMath	Dredge and life-saving appliances in first-class order	24/7/01.
			Dredge closed down; appliances in good order	17/8/01.
Leaning Rock ..	Leaning Rock Gold-dredging Company	D. Murray	Ready to start, but not yet equipped with life-saving appliances..	17/8/01.
Monte Christo ..	Monte Christo Gold-dredging Company	T. Keen ..	Light-lines and two boat-hooks required. Company notified that second boat, lately belonging to the Golden Falls, was unsuitable for river-work, and that a suitable boat would have to be provided	17/8/01.
Boundary Creek ..	Boundary Creek Gold-dredging Company	A. Gibson	Dredge and appliances in good working-order ..	17/8/01.
Half-way House ..	Half-way House Gold-dredging Company	J. Rogers..	Repairing; dredge and appliances in good order	7/12/01.
		A. Young..	Belt-drive and bevel gear for screen require to be guarded	24/7/01.
		F. Williams	Dredge and appliances in good order ..	17/8/01.
Kelly and Casey ..	Kelly and Casey Gold-dredging Company	T. Brown..	Dredge and appliances in good order; closed down temporarily	7/12/01.
Great Central ..	Great Central Gold-dredging Company	J. Robertson	Screen driving-gear requires to be covered; hand-rail required across the tables	24/7/01.
			Dredge and appliances in good order; rules observed ..	16/8/01.
Alpine Consols ..	Alpine Consols Gold-dredging Company	J. MacConnell	Gangway required across the well ..	24/7/01.
			Dredge and appliances in good order; not working	6/12/01.
			Dredge appliances in good order; regulations complied with	24/7/01.
			"	7/12/01.