WORKING DREDGES INSPECTED—continued.

Name of Dredge.	Ожпетв.	Dredgemaster.	Remarks.	Dates of Visits.
CLUTHA RIVER—continued. Clyde-Cromwell Gorge-continued. Alvine No. 2	Alvine No. 2 Gold-dredging Company	A. Johnston	Dredge and appliances in good order, and rules observed	26/7/01.
Hartley and Riley		McLay	Dredge and appliances in good order; regulations complied with	7/12/01, $31/7/01$ .
Junction-Electric No. 2, Cromwell		A. Ross	Dredge and appliances in fair order	16/8/01.
Above Gromwell. Royal Maori	Royal Maori Gold-dredging Company	F. Kitto	Gangway required across well-hole, also some fencing aft; runners to be provided for boat-	30/9/01.
Rise and Shine	Rise and Shine Gold-dredging Com-	D. Cormack	detting ready to start; to be provided with life-saving appliances	7/12/01.
Point d'Or	Point d'Or Gold-dredging Company	M. Murray	Requires new second boat; otherwise appliances in good order	6/12/01.
Below Albertown. Upper Clutha Prince Albert	Upper Clutha Gold-dredging Company Prince Albert Gold-dredging Company	A. Gibson J. Parsons	Getting ready to start; no boats on the claim; no life-saving-appliances on board Company notified on 6th December, 1901, that second boat unfit for river-work, and that a proper hoat should he provided. Two buoys and three boat-hocks required	2/12/01. $15/10/01$ ; $2/12/01$ .
KAWARAU RIYER. Above Cromwell. Central Electric	Central Electric Gold dredging Com-	J. Ledingham	One boat-hook short; otherwise regulations well observed	26/7/01.
Electric Extended	pany Electric Extended Gold-dredging Com-	J. Sanders A. Bremner	Shifting up stream; appliances in good order 200 ft. light-line required; otherwise dredge in good order	4/12/01. 30/7/01.
Junction-Electric No. 1.	Junction-Electric Gold-dredging Com-	A. Hedley	Second boat unfit for river work; has since been replaced by one more suitable. Appliances	16/8/01.
Gromwell Electric (Lady Ranfurly)	pany Gromwell Gold-dredging Company Electric Gold-dredging Company	N. P. Kloogh J. Steel	Dredge and appliances in first-class order, and regulations well observed  Main rope-drive to be guarded; otherwise dredge in good order	30/7/01. 30/7/01.
Kawarau Gorge.  Magnetic Second Magnetic	Magnetic Gold-dredging Company Second Magnetic Gold-dredging Com-	W. Kitto J. F. Kitto	Dredge and appliances in good order and condition Railing required across the tables; appliances in good order	31/7/01. 31/7/01.
Upper Magnetic	pany Upper Magnetic Gold-dredging Com-	J. Rae	Dredge and appliances in good order	31/7/01. 96/11/01.
Meg and Annie	Meg and Annie Gold-dredging Com- pany	D. J. McIntosh J. McDonald	Well-fencing pulled down; hand-rails required on well-gangway  Working with only one boat; three boat-hooks missing; well-fencing down; regulations	31/7/01. 26/11/01.
Grbbston	Merrimac Gold-dredging Company	D. McLean	not posted; gangway required over well Dredge and appliances in good order, but boating-work difficult; gorge narrow, and river	1/8/01.
Galvanio Eclipse	Galvanio Gold-dredging Company Eclipse Gold-dredging Company	Position vacant R. Woods	Very tappu.  This dredge refitting after being sunk An additional life-belt required; otherwise dredge and appliances in good order  Dredge and appliances in good order	31/7/01. 1/8/01. 25/11/01.
Above Kawarau Bridge. Kawarau Bridge	Kawarau Bridge Gold-dredging Com- pany	J. H. Robertson	Gangway required over well-hole, and hand-rail across tables; light-lines and boat-books required  Not quite up to regulation mark yet	2/8/01. 15/8/01.