Working Dredges inspected—continued.

Name of Dredge.	Owners.	Dredgemaster.	Remarks.	Dates of Visits.
Kawarau Biyer—continued. Above Kawarau Bridge—contd. Arrow Junction Kia Ora, below Frankton	Arrow Junction Gold-dredging Có Kia Ora Gold-dredging Company	J. Highet G. S. Morris	Well-gangway required; also some light-lines Getting ready to start; life-saving appliances ordered, but not on board	2/8/01. 21/11/01.
Dart River, 25 miles above Glenorchy	Dart River Prospecting Company	J. Нау	Port side rail required forward; hand-rail to be fixed for ladder-way to the boxes; life-belts not on board; three boat-hooks required	6/8/01.
CARDRONA VALLEY. White Star, below Branch Creek Cardrona No. 1		M. Murray F. C. McClure	Dredge and appliances in good order	27/4/01. 27/4/01.
Tacon's Cardrona	pany Tacon's Cardrona Gold-dredging Com- James Lowe pany	James Lowe	Fly-wheel of engine requires to be fenced; otherwise dredge in good order	27/4/01.
Nevis River. Nevis. Success	Success Gold-dredging Company	D. McIntosh	No life-buoys, light-lines, or boat-hooks on board	1/5/01.
Carrick	Carrick Gold-dredging Company	J. Thomson	Standing	$\frac{27/11/01}{1/5/01}$.
Nevis	Nevis Gold-dredging Company	J. Mitchell	No lite-buoys, itencing escellent in good order; itencing escellent in Board in a context in a c	$\frac{27}{11/01}$. $\frac{27}{11/01}$. $\frac{30}{4/01}$.
Ngapara No. 2	Ngapara Gold-dredging Company	J. McLean	only one buoy on board; therwise dredge in good order.	27/11/01. 30/4/01.
Ngapara No. 3	Ngapara Gold-dredging Company	McDonald	Only one buoy on board; light-lines and boat-hooks required	27/11/01. $30/4/01$.
Remarkables	Remarkables Gold-dredging Company	o. McLeau C. Robertson		27/11/01. $27/11/01$.
BANNOCKBURN. Shepherd's Creek, Shepherd's Creek Bannockburn Creek, Bannock-burn Creek	Shepherd's Creek Gold-dredging Com- pany Bannockburn Creek Gold-dredging Company	F. Woodhouse G. S. Morris	Repairing Guard required round winch engine; no boat in paddock Dredge just started; no life-saving appliances on board; elevator-gangway requires hand. Trails on outside	25/7/01. 30/11/01. 1/5/01.
MANUHERIKIA RIVER. Golden Link, Alexandra	Golden Link Gold-dredging Company	W. Poulter	Bailing required forward; otherwise dredge and appliances in good order	25/1/11. 3/6/01.
Manorburn, above Alexandra Morning Star, above Alexandra	Manorburn Gold-dredging Company Morning Star Gold-dredging Company	H. Leicester W. Mason	Delig raised after sinking "Bengir ilfe hings to be remained of life line and best in renair ilfe hings to be sent in renair ilfe hings to be sent in renair ilfe hings."	22/1/01. 6/6/01. 6/6/01.
Olrig, Springvale	Olrig Gold-dredging Company	E. A. Johnston	Regulations posted, but defaced; new copy required Boat not in paddock; otherwise dredge and appliances in good order	zə/1/01. 7/6/01.
Lindis River. Pioneer-Eureka	Pioneer-Eureka Gold-dredging Com- pany	James Watson J. Everitt	Prospecting-dredge on Lindis River; new dredge to be put on if ground proves payable Life-buoys, light-lines, and boar-hooks required; well-hole to be fenced; bevel gearing on elevator to be guarded; fencing required round unprotected parts of pontoons. Secretary was notified on 15th October, 1901, to attend to above	29/4/01. 3/10/01.