WORKING DREDGES INSPECTED—continued.

Name of Dredge.	Owners.	Dredgemaster.	Remarks.	Dates of Vis ts.
Kawabau River—continued. Kawarau Gorge. Electric No. 2 Voltsic	7. Electric Gold-dredging Company Voltaic Gold-dredging Company	A. Hedley W. Stevens	Guard fly-wheel and screen driving gear; one buoy required	6/11/02. 27/5/02.
Upper Magnetic	Annie Queen Gold-dredging Co.	J. Ritchie	lines required; screen-pinions and fly-wheel to be guarded; bar required across coal-door Dredge and life-saving appliances in good order 200 ff. of heaving-line and two boat-hooks required Ganguage required across the well hale and severe divine-cear to be guarded hows of second	19/7/02. 25/2/02. 93/7/09
Gentle Annie	Gentle Annie Gold-dredging Company	D. McLean	Dredge and life-saving appliances in good order  New dredge ready to start work  Dredge and life-saving appliances in good order  New dredge saving appliances in good order  Fence screen driving gear; well-hole and forward fencing down; well-hole gangway not in	25/1/02. 25/2/02. 7/4/02. 19/7/02.
Meg and Annie	Meg and Annie Gold-dredging Com-	E. McDonnell	position; heaving-lines required; two buoys, 14 in. inside measurement, too small  Dredge and life-saving appliances in good order  Guard screen driving-gear; fence main belts and rope-drive; well-hole gangway not in position; heaving-lines and one boat-hook required; one buoy, 14 in. inside measurement,	25/7/02. 25/2/02. 22/7/02.
:	Grand Junction Gold-dredging Com-	A. Young	too small Dredge and life-saving appliances in good order Guard fly-wheel and main belt; provide stern fencing and approach to elevator Dredge and life-saving appliances in good order	25/10/02. 25/10/02. 28/10/02.
Galvanic	Merrimac Gold-dredging Company Golden Molyneux Gold-dredging Co. Galvanic Gold-dredging Company	Caretaker T. Spain J. Richmond	Dredge standing	22/2/02. 29/10/02. 22/2/02. 22/7/02.
Gibbston Edinse	Gibbston Gold-dredging Company	A. Steel B. Woods	small Regulations not posted; dredge stopped for alteration; the second boat, which had been a ship's boat, is unsuitable for river-work, and has been condemned Dredge and life-saving appliances in good order: the cork tackets in use are rather heavy	29/10/02.
Above Kawarau Bridge. Kawaran Bridge	Kawarau Bridge Gold-dredging Com-	Ç.≼	for convenience in working  Dredge and life-saving appliances in good order  Dredge moored in safe position	22/7/02. 24/2/02.
Arrow Junction Kia Ora	pany Arrow Junction Gold-dredging Co Reid and party Kia Ora Gold-dredging Company	ଜୁନ୍ନ	Gangway required across well-hole; two more life-belts required Guard main fly-wheel, and use the well-hole gangway  Reg. 83, Rule 1, disregarded; elevator driving-gear to be guarded; port bow-line fair lead to be shifted: the second boat, 12 ft. in largth by 5 ft. beam by 2 ft. 6 in, in depth. has been	22/7/02. 24/2/02. 21/7/02. 24/2/02.
Kia Ora	Golden Vein Gold-dredging Company	A. Bremner	condemned as unfit for river-work  Dredge standing; dredge and life-saving appliances in good order and repair	24/5/02.
SHOTOVER RIVER. Prince Arthur	Prince Arthur Gold dredging Company	J. Kitto	New dredge getting ready for work	19/5/02.
Maori Point	Maori Point Gold-dredging Company	J. Hoskins	Well-hole fencing not erected; main belts and fly-wheel to be guarded; the second boat is too light and narrow for river-work, and has been condemned. Dredge and life-saving appliances in good order; suitable second boat not yet provided. Dredge and life-saving appliances in good order; the large boat was lying on the beach Large boat now at the dredge.	