

WORKING DREDGES INSPECTED—continued.

Name of Dredge and Locality.	Owners.	Dredgemaster.	Remarks.	Dates of Visits.
<i>CLUTHA RIVER—continued.</i>				
<i>Alexandra—continued.</i>				
*Chicago ..	Chicago Gold-dredging Company ..	William Poppelwell	Guard-rails required across tables, and on forward well-hole	17/9/03
*Sandy Point (Glasgow dredges)	Sandy Point Gold-dredging Company ..	A. Steel	Dredge repairing; life-saving appliances in fair order	15/8/03
*Perseverance No. 1 ..	Perseverance Gold-dredging Company ..	S. Cameron	Large boat not thoroughly equipped; hand-rail required for well-hole gangway	17/2/03
	Ditto ..	"	Well-hole gangway and hand-rails required; three boathooks missing	15/8/03
*Perseverance No. 2 ..	" ..	"	Dredge undergoing repairs	17/2/03
	" ..	"	Repairing	15/8/03
*Dunstan Lead ..	Dunstan Lead Gold-dredging Company ..	D. Bringans	Dredge and life-saving appliances in first-class order	17/2/03
	" ..	"	"	15/8/03
<i>Below Clyde.</i>				
*Matau ..	Matau Gold-dredging Company ..	H. P. Sanders	Dredge and life-saving appliances in good order	17/2/03
*Unity ..	Unity Gold-dredging Company ..	T. Barry ..	"	15/8/03
	" ..	"	Cover required for screen driving-gear; otherwise dredge and life-saving appliances in good order	17/2/03
	" ..	"	Visited dredge in connection with fatal accident to William H. Hughes, engineer, on the 27th February, particulars of which appear on list appended	17/2/03
*New Vincent ..	New Vincent Gold-dredging Company ..	W. Kane (caretaker)	Set-screw on screen roller-shaft to be guarded; otherwise dredge and life-saving appliances in good order	5/3/03
	" ..	"	Dredge undergoing extensive overhaul	23/9/03
<i>Clyde to Cromwell Gorge.</i>				
*New Dunstan ..	New Dunstan Gold-dredging Company ..	"	Dredge idle	5/3/03
	" ..	"	"	23/9/03
*Davis Bend No. 2 ..	Davis Bend Gold-dredging Company ..	J. R. Baker	"	18/2/03
(late New Dunstan)	" ..	Thomas Hogg	Dredge and life-saving appliances in good order	17/5/03
*Leaning Rock ..	New Bendigo Gold-dredging Company ..	L. Anderson	Lately Leaning Rock dredge; being removed to new Bendigo claim, below Alexandra	23/9/03
*Monte Christo ..	Monte Christo Gold-dredging Company ..	T. Keen ..	Dredge and life-saving appliances in good order	16/2/03
	" ..	J. Hewitt	Fly-wheel guard not in position; platform required about top gear; second boat not equipped; buoy on bows too small	16/2/03
*New Halfway House ..	New Halfway House Gold-dredging Company ..	Caretaker	Dredge and life-saving appliances in good order	23/9/03
	" ..	J. Sawle ..	"	16/2/03
*Kelly and Casey ..	Kelly and Casey Gold-dredging Company ..	T. Hogg ..	Dredge shifting up-stream; recommended that extra precautions be taken before attempting to pull through the rip; two buoys falling to pieces. This dredge has since been sold to Alexandra Eureka Company, and is now known as Alexandra Eureka No. 2 dredge	24/9/03
	" ..	"	Machinery removed to Waikata; pontoons high and dry; these pontoons have since been pulled to pieces	16/2/03
*Great Central ..	Lately Great Central Gold-dredging Company ..	Caretaker	Dredge and life-saving appliances in good order	16/2/03
*Alpine Consols ..	Alpine Consols Gold-dredging Company ..	R. B. Denniston	"	24/9/03
*Riley's Beach ..	Riley's Beach Gold-dredging Company ..	J. Watt ..	Set-screw on tension-pulley not guarded; stern railing down; three lifebelts required	16/2/03
*Alpine No. 2 ..	Alpine No. 2 Gold-dredging Company ..	M. Murray — Johnston	Dredge idle; awaiting favourable fall of river	24/9/03
*Hartley and Riley ..	Hartley and Riley Gold-dredging Company ..	G. McLay	Dredge and life-saving appliances in first-class order	24/9/03
*Central Electric ..	Central Electric Gold-dredging Company ..	K. M. Woods	50 ft. of heaving-line required for stern	25/5/03
	" ..	"	Dredge idle; this dredge has been acquired by the Sunshine Gold-dredging Company, Lowburn	24/9/03
	" ..	"	"	25/5/03