

No. 3.—RETURN of NOTICES given to REPAIR BOILERS—*continued.*

Number.	Type.	Description of Repairs.
1	Multitubular	Girder fitted to carry weight of boiler.
4	"	Manhole-doors repaired.
2	"	New dogs and studs in mud-door.
1	"	New end fitted in steam-dome.
2	"	New flanges fitted to bottom of steam-dome.
7	"	New manhole-doors.
1	"	New manhole-door, and patch riveted on crown of boiler under safety-valve chest.
14	"	New mud-doors.
12	"	New studs and nuts for mud-doors.
1	"	One new stay-tube and three plain tubes fitted.
1	"	One plate renewed in bottom of shell.
2	"	Patches riveted on shell under blow-off cock.
1	"	Patch riveted over circumferential seam at back end, and two new tubes.
14	"	Retubed.
1	"	Retubed, and patch riveted on shell under blow-off cock.
1	"	Retubed, new manhole and new mudhole doors.
1	"	Stay-tubes renewed and manhole-door repaired.
1	"	Thirteen new tubes.
1	"	Three new longitudinal stays.
1	"	Three new tubes.
1	"	Three defective rivets taken out of gusset-stay, and three turned bolts fitted in.
1	"	Two broken rivets taken out of shell, and two turned bolts fitted.
1	"	Two new longitudinal stays.
1	"	Two patches fitted to bottom of tube-plate.
1	Portable	Compensating-rings fitted to manhole-openings.
30	"	Compensating-rings fitted to mudhole-openings.
1	"	Coupling pins in end of longitudinal stays renewed.
1	"	Crank-bracket refastened to boiler.
2	"	Crown of firebox cut out and new crown fitted.
3	"	Cylinders rejoined to crown of boiler.
3	"	Eight new screwed stays in firebox.
1	"	Eight new tubes.
1	"	Five new longitudinal stays.
1	"	Four new longitudinal stays and doubling plate fitted.
1	"	Four new sling-stays fitted to crown of firebox and compensating-rings fitted to all mudhole-openings.
3	"	Foundation-rings patched.
2	"	New dog stud and nut for mud-door.
1	"	New girders and stays on crown of firebox, and compensating-rings fitted to mudhole-openings.
3	"	New girders and stays on crown of firebox.
1	"	New girders on crown of firebox and twelve new tubes.
3	"	New screwed mud-plug in front tube-plate.
2	"	New longitudinal stays and three stay-tubes.
1	"	New longitudinal stay and one patch in firebox, also three patches on shell.
7	"	New mud-doors.
1	"	New mud-plugs.
1	"	New palm-stays.
1	"	New stays on crown of firebox.
16	"	New studs and nuts fitted to mud-doors.
1	"	One new longitudinal stay.
1	"	One new tube.
1	"	Patch fitted on front of boiler over crack.
1	"	Patch fitted on front tube-plate, and new mud-plug.
2	"	Patch fitted over thin place in front tube-plate.
3	"	Patch fitted round skirting in firebox.
4	"	Patch fitted over defective parts in firebox.
3	"	Patch fitted on shell of boiler under blow-off cock.
1	"	Patch fitted on bottom of shell, and compensating-rings on all mud-doors.
1	"	Part of firebox cracked, was chain-pinned.
10	"	Retubed.
1	"	Retubed and new screwed stays in firebox.
1	"	Retubed, new firebox-crown and new girder-stays.
1	"	Retubed, new firebox and new screwed stays.