No. 17.—RETURN of VESSELS SURVEYED for SEAWORTHINESS—continued.

| Date of Survey. | Name of Vessel. | Where surveyed. | Nature of Casualty, &c. | | | |
|--------------------|-----------------|-----------------|--|--|--|--|
| 1907. Mar. 8 | S.S. Rimu | Invercargill | Whilst this vessel was on a voyage from Patterson Inlet to Half-moon Bay or the 15th February she grounded in Paterson Inlet. On the vessel's arrival at Invercargill a diver was employed to examine the hull. He reported that no damage had been done. An internal examination was also made by a surveyor, | | | |
| Mar. 8 | ,, Rakiura | Dunedin | when it was found the vessel had received no injury. Whilst on a voyage from Dunedin to Waikawa the vessel ran ashore at 1.30 a.m. of the 16th February in Wiltshire Bay upon a sandy beach. She remained aground until the 7th March, when she was refloated on a good tide. | | | |
| Mar. 15 | ., Storm | Dunedin | She returned to Dunedin, where a survey was made of the vessel, when it was found she had received no injury. The chief engineer of this vessel reported that a flaw had developed in the after crank-pin of the crank-shaft of the main engines. At the survey it was discovered that the flaw was | | | |
| | | | showing distinctly on both sides of the pin. It was decided to have a new crank-shaft made to replace the defective one. The vessel was allowed to run until the new shaft was ready. | | | |
| Mar. 20 | Mararoa | Wellington | A defect was discovered in one of the lengths of the main steam-pipe of this vessel on the 18th instant whilst on a voyage from Wellington to Lyttelton. Temporary repairs were made to the pipe on the vessel's arrival in Lyttelton, enabling the vessel to return to Wellington. The pipe was taken off in Wellington and thoroughly repaired, and was afterwards tested under hydraulic pressure to 320 lb. per square inch before being placed on board. | | | |

No. 18.—Return showing the Revenue from the Inspection of Machinery Department (including the Examination of Marine Engineers and Land-engine Drivers, and the Amount earned by the Survey of Steamers and Sailing-ships), also the Ordinary Expenditure of the Inspection of Machinery Department (including the Examination of Marine Engineers and Land-engine Drivers and Survey of Steamers and Sailing-ships), during the Financial Year ended the 31st March, 1907.

| Rèce $ipts$. | £ | g, | đ. | Expenditure. | | £ | s. | đ. |
|--|--------|----|----|--------------------------------------|----|--------|----|----|
| Inspection of boilers and machinery (less | | | | Salaries | | 5,994 | 12 | 10 |
| refunds) | 6,802 | 14 | 10 | Advertising | | 26 | 11 | 10 |
| Certificates of land-engine drivers (less re- | | | | Furniture for offices | | 10 | 6 | 6 |
| funds) | 651 | 2 | 6 | Gas | | 3 | 2 | 0 |
| Survey of steamers (including auxiliary- | | | | Postage and telegrams (three months) | | 61 | 10 | 5 |
| powered vessels) | 1,849 | 10 | 0 | Rent-Cleaning offices and fuel | ٠. | 285 | 18 | 8 |
| Survey of sailing-ships | 84 | 0 | 0 | Telephone rents | | 43 | 0 | 0 |
| Survey of vessels for seaworthiness | 138 | 0 | 0 | Travelling allowances and expenses | | 2,295 | 9 | 1 |
| Examination of marine engineers (less re- | | | | Contingencies | | 169 | 8 | 10 |
| funds) | 195 | 10 | 0 | ** | | | | |
| , | | | | | | | | |
| and the second s | £9,720 | 17 | 4 | | | £8,890 | 0 | 2 |
| | | | | | | | | = |