

No. 3.—RETURN of NOTICES given to REPAIR BOILERS—*continued*.

Number.	Type.	Description of Repairs.
2	Portable	Two sight-holes retapped, and new tapered plugs fitted.
1	"	Upper row of screwed stays in throat-plate renewed.
1	Semi-portable	Ferrules fitted to tube-ends.
1	"	New dog fitted to mud-door.
2	"	New stud in front mud-door.
1	"	Patch fitted in firebox, and one new screwed stay.
1	"	Several new screwed stays in firebox, two sight-holes cut and tapered plugs fitted.
1	Semi-tubular	Circumferential seams caulked, galloway-tube repaired, and five new longitudinal stays fitted.
1	"	Furnace-crown repaired.
1	"	New foundation fitted under boiler.
5	"	Retubed.
5	"	Retubed, and new tube-plate fitted.
1	"	Six rivets renewed in back tube-plate.
1	"	Three new tubes.
1	"	Tubes drawn, and tube-plate cleaned.
2	"	Two new corrugated furnaces fitted.
1	Traction	A number of new screwed stays in firebox.
1	"	All new screwed stays fitted in firebox.
1	"	Bottom of front tube-plate reriveted.
7	"	Compensating-rings riveted to mudhole-openings
1	"	Crown seams in firebox reriveted.
2	"	Firebox crowns repaired.
1	"	Forty new screwed stays in firebox.
1	"	Four new screwed stays in firebox.
1	"	Four new screwed stays in throat-plate.
1	"	Four new tubes.
1	"	Fourteen new tubes.
1	"	Laminated plate cut out of firebox-side and patch fitted.
1	"	New coupling-pins fitted in longitudinal stays.
2	"	New crown in firebox, and new stay-tubes.
1	"	New stud in mud-door.
1	"	One new screwed stay, and crack in firebox-chain pinned.
1	"	Patch fitted on crown of firebox.
1	"	Patch fitted on shell under blow-off cock.
1	"	Patch fitted on side of firebox.
18	"	Retubed.
1	"	Retubed, and compensating-ring fitted to manhole-opening.
1	"	Retubed, and fourteen new screwed stays in firebox.
1	"	Retubed, and new crown in firebox.
2	"	Retubed, and new firebox fitted.
1	"	Retubed, new firebox, and new front plate fitted.
1	"	Retubed, new firebox, two new stay-tubes, one new longitudinal stay, and front tube-plate reriveted.
1	"	Seven new tubes, and patch fitted on shell under blow-off cock.
2	"	Sight-holes in front plate retapped, and new tapered plugs fitted.
1	"	Ten new screwed stays in firebox, and small crack chain-pinned.
1	"	Three new tubes.
1	"	Twelve new screwed stays in firebox.
1	"	Two patches fitted over cracks, two new longitudinal stays, new handhole and door.
2	Vertical cross-tube	Compensating-rings fitted round manhole-openings.
8	"	Compensating-rings fitted round mudhole-openings.
1	"	Crown of firebox and cross-tube patched.
1	"	Foundation-ring round bottom of firebox repaired.
4	"	Four new vertical stays fitted between crown of boiler and crown of firebox.
1	"	New bottom fitted to firebox, new cross-tube, and new uptake.
1	"	New cross-tube.
1	"	New stud fitted to mud-door.
3	"	New uptake fitted.
1	"	New uptake fitted, and centre of boiler-crown renewed.
2	"	Patch fitted on shell under check-valve.
1	"	Patch fitted round bottom of firebox, and mudhole-openings compensated.
1	"	Patch fitted under safety-valve chest, and a number of new screwed stays.
1	"	Patch fitted under steam-pipe flange.