

No. 3.—RETURN of NOTICES given to REPAIR BOILERS during the Financial Year ended the 31st March, 1908.

Number.	Type.	Description of Repairs.
1	Cornish	Brickwork repaired.
2	"	Furnaces patched where wasted.
1	"	Furnace seams caulked.
1	"	Gusset-stay repaired.
1	"	Patch fitted on shell-plate above furnace.
1	"	Two rivets renewed in furnace.
1	Cornish tubular	New length of flue fitted in front end.
1	"	Patch fitted in furnace.
2	"	Retubed.
1	"	Retubed and new back tube-plate.
1	"	Strengthening-rings fitted to furnace.
1	"	Three patches renewed.
1	"	Twenty-four tubes renewed.
1	"	Twenty-two plain and four stay tubes renewed.
1	Dryback marine	Furnace-crown repaired.
1	"	Tubes expanded, and patch fitted on back end plate in steam space.
1	"	Two new tubes.
1	Lancashire	Furnaces repaired.
1	"	Patches fitted over grooving at front end of right-hand furnace and back end of left-hand furnace.
1	"	Six defective rivets renewed.
1	"	Strengthening-rings fitted round furnace.
1	"	Two new furnaces fitted.
2	Locomotive	A number of new screwed stays fitted in firebox.
1	"	Back ring of furnace repaired.
1	"	Crown stay-nuts renewed.
1	"	Five new tubes fitted.
1	"	Foundation-ring at front end riveted.
1	"	Lower part of firebox renewed, and twenty-two new screwed stays fitted.
1	"	New firebox, and all new screwed stays fitted.
1	"	New front tube-plate and new longitudinal stays fitted.
1	"	New girders fitted to crown of firebox.
1	"	New tube-plate fitted.
1	"	One new longitudinal stay fitted and one new mud-door.
1	"	Patch fitted on bottom of shell.
1	"	Patch fitted on crown of firebox, and one new longitudinal stay.
1	"	Patch fitted on each side of firebox.
3	"	Patches fitted in firebox.
1	"	Patch fitted on throat-plate.
2	"	Retubed.
1	"	Retubed, and new tube-plate.
1	"	Six new screwed stays in firebox.
1	"	Sixteen new tubes fitted.
1	"	Sixteen new tubes, one new screwed stay in firebox, and three new nuts fitted on crown-stays.
1	"	Three new screwed stays in firebox.
1	"	Three new tubes fitted.
1	"	Top row of screwed stays at back end of firebox renewed.
1	"	Twelve new screwed stays fitted in firebox, and one new mud-door.
1	"	Twenty new nuts fitted on girder-stays.
1	"	Twenty-six new tubes fitted.
1	"	Two new tubes fitted.
1	"	Two rivets renewed and patch fitted in firebox.
1	Manure-dryer	Four feet of sheathing fitted to the bottom of inside shell.
1	"	New bottom plate fitted.
1	"	Sheathing-plate fitted on bottom.
1	"	Two sheathing-plates fitted on bottom.
2	Marine ...	Retubed.
1	"	Several tubes expanded.
2	Multitubular	All tubes expanded.
1	"	Bolted patch rejoined to shell.
25	"	Brickwork repaired.
7	"	Bulge cut out of bottom of shell and a patch fitted and riveted on.
1	"	Bulge cut out of bottom of shell at back end, patch fitted and riveted on, and all tubes drawn to clean boiler.
3	"	Compensating-rings fitted round manhole-openings.
2	"	Compensating-rings fitted round mudhole-openings.