No. 3.—RETURN of Notices given to REPAIR BOILERS—continued.

Number.	Type.	Description of Repairs.
4 1	Traction Vertical cross-t	Two new screwed stays put in sides of firebox. Bottom part of shell and furnace renewed, and a row of ne
_		screwed stays round furnace.
8	, ,	Compensating-rings fitted round mudhole-openings.
2	"	Crown of boiler patched.
1 1	"	Four new vertical stays fitted, and patch under safety-valve chest
2	"	Laminated plate in furnace patched New collars fitted on crown of boiler round uptake.
ī	" "	New foundation-ring fitted.
ī	, "	New manhole-door.
1	,,	New spigot fitted to manhole-door.
2	,,	New uptakes fitted.
1 1	,,	One new vertical stay and mudhole-opening compensated Patch fitted on bottom of firebox.
1	"	Patch fitted on bottom round foundation-ring.
ī	"	Patch fitted round bottom of firebox, and mudhole-openings con
1	"	pensated.
1	,,	Patch fitted under stop-valve chest, and a row of new screwed stay
		round firebox.
2	"	Rivets in top of uptake renewed.
$\begin{bmatrix} 1 \\ 2 \end{bmatrix}$	"	Seventeen new screwed stays put in firebox. Several rivets renewed in shell of boiler.
1	"	Three new vertical stays fitted, and a row of new screwed stay
- !	"	round firebox.
1	"	Two patches fitted to vertical landings in firebox.
1	Vertical field tu	
1	"	New manhole-door, and several new tubes fitted.
1	"	Patch fitted on bottom of firebox. Patches fitted on shell under blow-off cock.
2 1	"	Retubed.
2	Vertical flue	Compensating-rings fitted round mudhole-openings.
1	"	Four compensating-rings fitted round mudhole-openings.
1	"	New manhole-door fitted.
3	"	New mudhole-doors fitted.
1	#	New spigot fitted to manhole-door.
1	"	New uptakes fitted Part of firebox renewed.
i l	"	Patch fitted in firebox under door.
ĩ	"	Patch fitted round bottom of uptake.
1	"	Three new vertical stays fitted.
1	"	Vertical stays rejointed.
1	374:1 4h1	Wasted part of uptake patched.
1 1	Vertical tubular	Centre stay renewed Compensating-rings fitted to manhole and mudhole openings.
9	"	Compensating-rings fitted round mudhole-openings.
2	"	Four new vertical stays fitted.
1	 #	New manhole-door fitted.
1	"	New manhole-door, and a row of new screwed stays in firebox.
1	,,	One new stay-tube and three new screwed stays fitted.
4 2	"	One new tube fitted One new vertical stay fitted.
1	"	Patch fitted in firebox.
i	"	Patch fitted under safety-valve chest.
16	" "	Retubed.
1	"	Retubed, and compensating-rings fitted round mudhole-openings.
1	,,	Retubed, and new top tube-plate.
1	"	Retubed, new top tube-plate, and patch fitted to shell of boiler.
1	"	Several tubes expanded Six new tubes fitted.
1	"	Three compensating-rings fitted to mudhole-openings.
i	"	Twelve net rivets put in skirting.
1	,,	Two new tubes fitted.
2		Two patches fitted round bottom of shell.
1	Water-tube	Bottom row of tubes renewed.
2	"	Brickwork repaired.
2 1	"	One new tube fitted Twenty-seven bolts in caps for headers renewed.
2	" 	Two new tubes fitted.
	"	