DEFECTIVE FITTINGS found on Inspection of Boilers, for which Notice was given to renew or repair during the Financial Year ended 31st March, 1911.

- 1 Bends of blow-off cocks defective: were renewed.
- 1 Bends of feed-pipes defective: have been renewed.
- 8 Blow-off cocks bad: have been renewed.
- 4 Blow-off cocks defective: were repaired.
- 5 Blow-off pipes bad: have been renewed.
- 1 Brake-gear defective: has been put in order.
- 1 Crank-shaft of engine bent: was straightened. 1 Crank-shaft of engine fractured: was renewed.
- 2 Feed-check valve-chests and valves bad: have been renewed.
- 1 Feed-check valve defective: was renewed.
- Feed-pumps defective: was repaired.
- 17 Ferrules fitted under spring-balance safety-valve levers.
- I Flywheel of engine defective: was repaired.
- 19 Fusible plugs defective: have been renewed.
- 123 Guards fitted to water-gauge glasses.
 - 2 Injectors defective: were renewed.
 - 1 Main steam-pipe defective: was repaired.
 - 2 Main steam-pipe fitted with hangers.
- 13 Manhole-doors bad: have been renewed.
- Manhole-door studs bad: have been renewed.
- 33 Mudhole-doors bad: were renewed.
- 10 Mudhole-door studs bad: were renewed.
- New valve-chest fitted to feed-pump.
- New worms fitted to steering-gear.
- New worm-wheel fitted to stearing-gear.
- 2 Reducing-valves fitted.
- Safety-valves bad: were renewed. Safety-valves defective: were put in order.
- 3 Safety-valve springs bad: were renewed.
- Spring balances defective: new ones fitted.
- Steam-gauge pipes bad: were renewed.
- 1 Steam-pipe defective: was repaired.
- 40 Steam-pressure gauges defective: were renewed.
 - Steam stop-valve bad: was renewed.
- Steering-gear of traction-engine defective: was put in order.
- Steering-gear repaired and new brake fitted.
- Stop-valve cover defective: was renewed.
- 4 Tapered mud-plugs defective: were renewed. 15 Test-cocks bad: have been renewed.
- 6 Test-cocks defective: were repaired.
- 30 Water-gauge mountings bad: were renewed.
- 12 Water-gauge mountings defective: have been repaired.

3 Water-gauge pipes bad: were renewed.

Total .. 395

No. 3.—RETURN of NOTICES given to REPAIR BOILERS during the Financial Year ended the 31st March, 1911.

lumber.	Type.	Description of Repairs.
1	Cornish	 Bottom half of shell cut out, and new bottom plates fitted.
2	,,	 Brickwork repaired.
1	. ,,	 New gusset-stays fitted.
1	, ,,	 Several rivets renewed in flanges of cross-tubes.
1	,,	 Three rivets renewed in shell.
1	Cornish tubular	 Eight rivets in gusset-stays renewed.
1	,,	 One tube renewed.
1	**	 Patch fitted on furnace.
$ar{2}$,, ,,	 Retubed.
$ar{2}$,,	 Several bolts in gusset-stays renewed.
1	**	 Two patches fitted on bottom of boiler, and one new tube.
ī		 Two pins in longitudinal stays renewed.
1	Dryback marine	Four new rivets put in front of furnace.
1	,,	 Patch fitted on back tube-plate.
$ar{f 2}$	***	Retubed.
1		 Steam-dome reriveted.
î	"	 Three rivets in bottom seam renewed.