

No. 3.—RETURN of NOTICES given to REPAIR BOILERS—*continued*.

Number.	Type.	Description of Repairs.
5	Multitubular	New studs fitted in mud-doors.
1	"	Patch fitted at blow-off cock and compensating-ring mudhole opening.
1	"	Patch fitted on bottom of steam-dome.
1	"	Patch fitted on shell under blow-off cock.
1	"	Patch fitted on side of shell where casing bolts to boiler.
1	"	Patches fitted on tube-plates.
1	"	Patch fitted under main stop-valve chest.
2	"	Patches renewed.
1	"	Patch riveted on steam-dome, and patch on shell in front of dome.
6	"	Retubed.
1	"	Retubed, and new shell-plate fitted in bottom.
1	"	Retubed, and new longitudinal stay.
1	"	Several rivets renewed in shell.
1	"	Several new rivets put in manhole compensating-ring.
3	"	Several new tubes fitted.
1	"	Shell under steam-dome patched.
2	"	Ten new tubes fitted.
1	"	Thin portion of plate in bottom of shell cut out, and patch riveted on.
4	Portable	A number of new screwed stays fitted in sides of firebox.
1	"	All new screwed stays fitted in firebox, ten new tubes, and four new longitudinal stays.
1	"	Compensating-rings fitted to manhole-openings.
16	"	Compensating-rings fitted to mudhole-openings.
1	"	Compensating-rings fitted to mudhole-opening, and sixteen new screwed stays in firebox.
1	"	Compensating-rings fitted to mudhole-openings, and two new doors fitted.
1	"	Doubling-plate fitted round fire-door opening, and ten new screwed stays in firebox.
1	"	Eighteen new screwed stays fitted in firebox.
2	"	Eighty new screwed stays fitted in firebox.
1	"	Five new rivets put in circumferential seam at front end.
1	"	Forty new screwed stays fitted in firebox.
1	"	Fourteen new screwed stays fitted in firebox.
2	"	Hand-hole doors cut, and doors fitted for sighting.
2	"	Longitudinal stays fitted with new coupling-pins.
2	"	New girders fitted on crown of firebox.
1	"	New girders fitted on crown of firebox, and several new screwed stays fitted in firebox.
1	"	New manhole-door fitted.
4	"	New mudhole-doors fitted.
1	"	Patch fitted over crack in tube-plate.
3	"	Patches fitted on crown of firebox.
2	"	Patches fitted on foundation-ring.
2	"	Patches fitted on front of firebox.
1	"	Patches fitted on front of tube-plate.
1	"	Patches fitted on shell under blow-off cock.
1	"	Patches fitted on shell under check-valve chest.
1	"	Patches fitted under fire-door and on throat-plate, and all screwed stays in firebox renewed.
3	"	Patches in firebox renewed.
7	"	Retubed.
1	"	Retubed, and new tube-plate fitted.
1	"	Retubed, and six new screwed stays fitted in firebox.
1	"	Retubed, and thirteen new screwed stays fitted in firebox.
1	"	Retubed, and thirty new screwed stays fitted in firebox.
1	"	Seven new tubes fitted.
1	"	Seventy new screwed stays fitted in firebox.
6	"	Several new screwed stays fitted in firebox.
1	"	Sixteen new screwed stays fitted in firebox.
1	"	Twelve new screwed stays fitted in firebox.
1	"	Twenty new screwed stays fitted in firebox.
1	"	Twenty-six new screwed stays fitted in firebox.
1	"	Two new mud-doors fitted.
4	"	Two patches renewed.
1	"	Two patches on crown of firebox renewed, and eight new screwed stays fitted in firebox.