		RETU	RETURN OF	F WRECKS AND	CASUALTIES	ALTIES TO SHIP	בוואם ש	FING REFORIED IO THE MAI	שות שעות	MAKINE DEPARTMENT, E.C.	ETC.—continued.	
Vessel's Name,	3	-	Number of	ır of	Nature of	re of	Number of	ber Place where		Wind.		
Age, and Class.	M. S.	Regis ngoT	.wетЭ Б	Passen- gers. Cargo.		Casualty.	Lives lost.	Car	Direc- tion.	Force	rineing of Court of Inquiry.	Name of Masser.
Pakura, s.s., 4 years	Schooner	304	17	Nil General, 160 tons		Grounded	IIN :	Gisborne, N.Z.	S.W.	Fresh	When entering Gisborne River in tow of the tug "Pelican, vessel sheered to starboard, and the starboard bilge struck a bank about	C. W. Coldicutt.
Fairburn, o.e.v., 20 years	Schooner	9	ဗ	Nil General, 30 tons		Fire		Karamea Bight, N.Z.	Calm	:	200 ft. inside and opposite the breakwater, causing slight damage. Buginer was testing a spark-plug of the benzine electric-light engine; the spark-plug being unsorewed but connected and lying on the engine, it ignited some benzine	W. H. Sawyers.
Teine Vineula, aux., 8 years	Schooner.	79	9	10 General, 13 tons	<del></del>	Total loss	<b>.</b> :	Nukunonu, Union Is- lands	. N.E.	61	spiit on the engine. Fire put out promptly; no damage. While on a voyage from Atafu to Nukunonu, went ashore on reef. Evidence at preliminary inquiry stated Island of Nukunonu wrongly, charted. Ship abandoned after eighty days, attempt to refloat. Cargo	G. H. George.
Pahiki, sail, 21 years	Schooner	50	ന	Nil Shingle, 40 tons	·	Sunk at anchor		Hauraki Gulf, N.Z	. N.E.	Gale	salraged with exception of two bales of wool Sunk at anchor during gale. Accident could not have been avoided, as vessel was down	J. Grogan.
. <u>1</u> .	2									- 1 - 2	to straighten the cargo up. No damage. Vessel raised next day, and cargo landed in	* ***
Kamona, s.s., 25 years	F. and A.	806	25	Nil Coal, 1,897 tons		Fire	- FR - :	Greymouth, N.Z.	E.S.E.	<b>⇔</b>	g at wharf, smoke was found issuing to 1 hatch. Hatch opened up and nguished by ship's fire-hose. No	G. B. Hoddi- nott.
Kawau, s.s., 35 years	Schooner	37	ت ح	Nil Nil	:	Broken mast	.: Nil	1 Foveaux Strait, Rua- puke Island, N.Z.	E.N.E.	Breeze	damage Accident caused through snapping of a link of the chain attaching the rigging to ma.t.	J. I. F. Nixey.
										1.	vessel from a yard-arm supported by the mast. When the dredger fouled a rock, the rigging snapped at the chain, making the	
						a	· vac v			- :		
Kawau; s.s., 35 years Dispatch, s.s., 43 years	Schooner	37	עם עם	Nil Nii	: :	Collision	Nil	Foveaux Strait, Ruapuke Island, N.Z.	N.E.	Mòderate≺	dredgers were being hauled up a proper lookout was not maintained, there being no man at the wheel on either vessel. This appears to be a dangerous practice. When trouble was imminent, the "Kawau" was sent astern, but the reversing-gear of the Dispatch, jammed. Danage to "Dispatch," Engineer.	J. I. F. Nixey. A. W. Rouse.