

July 23	Success, o.e.v., 20 years	Cutter ..	2	2	Nil	Nil	..	Nil	Oamaru Harbour, N.Z.	N.E.	Strong	During a rough sea the range in the harbour wrenched the vessel from her mooring, and drove her on the rocks at the south-west corner of the harbour, where she was stove in and sank in 6 ft. of water. £60 damage. Ship found to be leaking port side forward; could not be avoided	A. Wardle.
Aug. 6	Tiroa, s.s., 11 years	Schooner	94	10	Nil	..	Leaking ..	Nil	King's Wharf, Auckland, N.Z.	W.	Fresh ..	The crank-shaft of the starboard engine broke; apparently unavoidable	L. W. Clark.
Aug. 11	Zita, s.s., 48 years	Schooner	73	8	Nil	..	Broken crankshaft..	Nil	42 miles S.S.W. Cape Egmont, N.Z.	N.W.	Strong..	Ship riding to a westerly swell; chain caught in ledge of reef; lost anchor and 30 fathoms of chain, which may be recovered	J. Francis.
Aug. 13	Hinemoa, s.s., 51 years	F. & A.	282	29	3	General, 82 tons	Lost anchor and 30 fathoms chain	Nil	Nuie Island	W.	Light ..	Ship riding to a westerly swell; chain caught in ledge of reef; lost anchor and 30 fathoms of chain, which may be recovered	A. R. Cant.
Aug. 13	Sittang, s.s., 16 years	Schooner	2,748	65	Nil	In ballast ..	Lost propeller ..	Nil	8 miles off Tairoa Heads, N.Z.	S.S.W.	4-5	While on a voyage from Dunedin to Westport, the vessel was felt to tremble violently, and "Stop" was immediately rung. Chief engineer reported that propeller was gone. Anchor was let go, and later vessel towed to Port Chalmers for repairs	G. Patterson.
Aug. 20	Opawa, s.s., 20 years	F. & A.	5,858	66	Nil	General, 8,000 tons	Shipped heavy sea	Nil	Lat. 33° 20' S., long. 159° 35' W., Pacific Ocean	W.N.	9	Shipped heavy sea forward. Damaged three ventilator-cowls and port wire-reel; carried away forward bell, and burst in two doors to crews quarters; ripped upper tarpaulins from No. 11 hatch. Vessel eased down, and ventilators and tarpaulins secured and lifeline rigged. Firemen's forecandle was flooded at after end. Men quartered in bridge space	D. Macmillan.
Aug. 21	Miro, o.e.v., 1 year	Ketch ..	29	5	Nil	Oats, 35 tons; explosives, 4½ tons	Fire ..	Nil	Lat. 44° 13' S., long. 172° 36' E., Pacific Ocean	N.	0-3	Fire in engine-room. Cause unknown. Supposed that tank overflowed on top of engine. Not discovered until fire taken hold. Damage to skylight and minor damage to electric-lighting circuit	H. T. Himainen.
Aug. 23	Clansman, s.s., 42 years	F. & A.	338	31	Nil	General, 160 tons	Collision	Nil	Auckland, N.Z.	N.E.	4	While the "Elsie Mary" was leaving King's Wharf, she accidentally collided with the "Clansman," piercing No. 4 lifeboat with her bowsprit	E. J. Keatley.
Aug. 23	Elsie Mary, sail, 25 years	Schooner	99	6	Nil	..		Nil	Between Dunedin and Timaru, N.Z.	S.	4	Between Dunedin and Timaru the low-pressure guide-rod end broke off. Eccentric strap disconnected, and engines worked compound	S. Hewitt.
Aug. 28	Wingatui, s.s., 12 years	Schooner	1,344	32	Nil	General, 1,000 tons	Guide-rod end broke	Nil	Lat. 39° 4' S., long. 170° 16' E., off N.Z. coast	W.N.W.	Strong ..	While on a voyage from Westport to Auckland, on soundings being taken, water was found to be in the forepeak. Examination from inside showed a small crack on edge of plate. No damage	J. Green.
Aug. 28	Karori, s.s., 23 years	F. & A.	1,194	30	Nil	Timber and coal, 2,675 tons	Leaking ..	Nil	Foxton bar, N.Z.	Var.	..	When crossing the Foxton bar, vessel grounded and remained fast; refloated later. No damage	A. McP. Stuart.
Sept. 2	Kennedy, s.s., 61 years	F. & A.	131	12	Nil	General, 77 tons	Grounded	Nil					