West Coast Inspection District.

Wynndale, Murchison. Mount Burnett, Collingwood. Puponga, Puponga. Owen, Owen River. Cardiff, Seddonville. Charming Creek, Ngakawau. Cascade, Burnett's Face. Chester's, Seddonville. Coal Creek, Seddonville. Hydro, Seddonville. Glencrag, Buller Gorge. Westport Coal Co.'s Denniston mines. Westport Coal Co.'s Millerton mines. Westport-Stockton, Ngakawau. Archer's, Capleston. Clele, Merrijigs. Coghlan's, Capleston. Collins, Murray Creek. Morrisvale, Reefton. Defiance, Reefton. Burke's Creek, Reefton. Waitahu Colliery, Reefton. Bennett's (Times Street), Reefton. Lankey's Creek, Reefton. Schultz Creek, Twelve Mile.

Kaye's, Ten Mile. Bellbird, Ten Mile. Brady's, Ten Mile. Briandale, Ten Mile. Cliffside (Moore's), Nine Mile. Bellvue, Rapahoe. Cain's, Rapahoe. Jubilee, Rapahoe. Baddeley's, Dunollie. Braehead, Dunollie. Castlepoint, Dunollie. Hunter's, Dunollie. Moody Creek, Dunollie. New Point Elizabeth, Dunollie. Fiery Cross, Dunollie. Smith's, Dunollie. Duggan's, Rewanui. Old Runanga, Rewanui. Spark's, Rewanui. State Collieries (Liverpool and James). Goldlight, Rewanui. Blackball, Blackball. Blackball Creek, Blackball. Paparoa, Roa. Dobson, Dobson. Wallsend, Brunnerton.

Southern Inspection District.

Kaitangata No. 2, Kaitangata. Wairaki, Ohai. Birchwood, Ohai. Linton, Ohai.

Hilltop, Ten Mile.

Black Diamond, Ohai. Black Lion, Ohai. Star, Ohai.

(c) List of Mines required by Law to use Safety-lamps.

The following is a list of the mines as at the 31st December, 1936, required by law to use safety-

Northern Inspection District.

Pukemiro, Pukemiro-Throughout South mine section. Rotowaro, Rotowaro—Throughout No. 1 and No. 3 Mines.

Glen Afton, Glen Afton—Main headings.

Renown, Waikokowai—Main headings and West Section turned off No. 4 North Section.

New Kamo, Kamo-East Section in neighbourhood of Fault.

West Coast Inspection District.

Dobson, Dobson. Spark's, Rewanui. State Mine (Liverpool No. 2), Rewanui. Moody Creek, Dunollie. Old Runanga (No. 2 Section), Rewanui. Paparoa, Roa. Wallsend, Brunnerton. Millerton (Old Dip Section), Millerton. Owen, Owen River.

Southern Inspection District.

Kaitangata No. 2, Kaitangata. Wairaki, Ohai. Birchwood, Ohai. Linton, Ohai.

Black Diamond, Ohai. Black Lion, Ohai. Star, Ohai.

(d) Dangerous Occurrences reported.

(Regulation 82.)

Of the twenty-nine dangerous occurrences reported during 1936 to the District Inspectors, twentyone were of actual fires or of heating in underground workings. Five were in the panels of the Millerton Mine, but one was caused by a lighted cigarette butt having been thrown on a small heap of decayed mine timber. Seven of the reports of spontaneous heating were of occurrences in the Linton Mine.

There were four reports of accumulations of inflammable gas and two reports of inrushes of water in West Coast coal-mines, and one report of an ignition of fire-damp in a Northern District mine. a Reefton mine the presence of a small percentage of hydrogen sulphide was detected in the mine-water.