| Date of | Vessel's Name. Class. | | Register | Num | Number of | | Nature of | ie of | | Numbe | | W | Wind. | | | 10 |
|------------------|--------------------------------|----------|----------|----------|------------------|--------------------|-----------|--------------------------|----------|----------|--|------------|------------|---|-----------------|----|
| Casualty. | and Age. | Kig. | Tonnage. | Crew. | Passen- gers. | Cargo. | | Casualty. | | of Lives | occurred. | Direction. | Force. | Remarks, or Finding of Court of Inquiry. | Name of Master. | • |
| 1937. Mar. 16 | Waimarino, s.s.; 7 years | Schooner | 1,752 | 31 | : | 400 tons general | : | Stranded | : | : | Bluff Harbour | Calm | : | When approaching No. 7 berth the vessel took the ground about 40 ft. from wharf. With the assistance of a tug the vessel | W. D. Cameron. | 1 |
| April 2 | Holmglen, m.v.; 9 years | Schooner | 290 | 12 | : | 15 tons general | : | Engine failure | : | : | South Taranaki Bight | N.W. | ıa | was renowich, and it was round that she had sustained damage. Owing to failure of one set of cooling-pipes the engines stopped. Temporary repairs | M. McArthur. | |
| ,, 18 | Aorangi, m.v.; 12 years | Schooner | 10,733 | 275 | • | 1,700 tons general | : | Fractured crankshaft-web | taft-web | : | Tasman Sea | : | ; | Were enected and the vessel put into Queen Charlotte Sound After the vessel had berthed at Auckland it was found that the starboard inner | T. Bill. | |
| ,, | Akaroa, s.s.; 23 years | Schooner | 9,461 | 164 | 89 | 2,597 tons general | | Damaged by heav | ry seas | : | Lat. 26° 25′ S.; Long. 177° 51′ W. (Pacific Ocean) | Ä | φ | No. 5 crankshaft, web has been fractured. The vessel shipped heavy seas over the forecastle head, breaking open No. 1 hadd somiting was No. 1 hadd somiting on No. 1 hadd somiting two No. 1 hadd somiting two No. 1 | W. C. Summers. | |
| ,, 27 | Thomas Currell, s.s.; 20 years | Schooner | ₹ | <u> </u> | : | 10 tons fish | | Leaky boiler | : | : | Off Matakana Island, N.Z. | W. | ** | nour-ventuations. Also introf damage to ship and fittings. It was discovered that the boiler had developed a leak in the combustion- chamber, and the vessel put into Tau- | J. Holt. | |
| May 1 | Doric Star, s.s.; 16 years | Schooner | 6,359 | 62 | : | General | : | Leaking | : | : | Auckland | • | • | ranga for repairs A leak was discovered in No. 6 'tween decks, | N. G. Oswald. | |
| : | Tees, s.s.: 26 years | Schooner | 247 | 17 | 11 | 1,000 sheep | : | Lost anchor and cable | sable | : | Pitt Island, Chatham Islands | W.N.W. | ro | causing damage to the cargo Owing to the vessel ranging, the starboard cable parted in hawse-pipe while the 45 fathom shackle was in the water. To be recovered on next visit to the Chat. | J. B. Allsop. | 12 |
| 10 | Pono, m.v.; 24 years | Schooner | 30 | # | : | General | : | Collision | : | : | Auckland Harbour | S.W. | Light | hams At 11.45 p.m. a launch was seen close on the starboard side and two green lights close on port side. Simultaneously some- thing was heard to have carried away, which was found to be the tow-line between a launch hamed the barge. "Kitty process." | N. Morgan. | |
| ,, 11 | Kawau, s.s.; 28 years | Ketch | 52 | 10 | • | 2 tons general | : | Loose propeller | : | : | Vivian Bay, Kawau Island | X.W. | Light | Traser, which bumped the "Pono," The "Kitty Fraser" was slightly damaged and the "Pono" sustained damage of her port bulwarks When engines going half-speed astern the propplier worked loose on the boss, and vessel had to be towed to Auckland for | J. V. Ruthe. | |
| ,, 15 | Robey, m.v.; 31 years | Cutter | 9 | çı | • | Towing only | ; | Stranded | | | Auckland Harbour | N.E. | Gale | repairs Owing to engine trouble, freshening wind and sea, and the parting of the tow-lines connecting the vessel with the barges 'Samoa' and "Argyle, 'He anchors of all three vessels were dronned in the | P. Baron. | |
| ,, 15 | Haere, m.v.; 34 years | Schooner | <u>o</u> | ນຕໍ | : | .: : | : | Stranded | : | : | Marsden Point, Whanga- | × · | Heavy gale | Tamaki Passage. Later all three vessels dragged and were driven ashore. The barges were successfully refloated, and efforts are being made to refloat the "Robey." Subsequently refloated. While the vessel was sheltering off Whangarel Heads, during a heavy gale the vessel commonced to drag her anchors, and at 10 pm. the vessel touched the rocks. The vessel was beached for safety and was subsequently refloated, apparently undamaged. | E. W. Norton. | |