

14	Dugan's	"	Dugan, H.	"	pitch	2	1' 11"	all	W 1 in 3	bord and pillar	...	drive	150	550	hand	...	...	15/4/80
15	Burke's	"	"	"	"	1	1' 8"	6'	N 30°	"	...	"	80	280	"	...	"	15/4/80
16	Oriental	"	"	"	"	1	3' 3"	all	S. 60° E.	"	...	"	none	...	"	...	"	14/12/80
17	Charleston, Charleston	"	"	"	"	...	...	all	S.W.	openwork	...	"	32,505	150,634	hand, and self-acting inclines	...	"	17/12/80
18	Brunner, Greymouth	"	Harrison, J., M.E., F.G.S.	"	16	1	12' to 16'	all	S.W. 1 in 3	bord and pillar	1	drive	14,330	42,043	engine 30 h.p.	4'	250'	16/12/80
19	Coal Pit Heath, Greymouth	"	Alexander, Thomas	"	4	1	16'	"	S.W. 1 in 4	"	2	shaft	none	12,122	engine 48 h.p.	5'	670'	18/12/80
20	Wallsend, Greymouth	"	Brown, Thomas	"	4	1	16'	"	S.W. 1 in 3½	"	1	"	604x	604x	15 u. 8 o.	10"	4	18/12/80
21	Wallsend, No. 2, Greymouth	"	"	"	...	1	17'	14'	S.W. 1 in 4	"	2	"	7,060	17,394	engine 10 h.p.	10"	3"	26/8/80
22	Springfield, Springfield	"	Bree, W R., C.E.	"	4	1	4'	all	S.E. 1 in 6 to 1 in 12	longwall	1	engine plane shaft	none	none	79 u. 18 o.	12"	20"	26/8/80
23	Springfield, No. 2, Springfield	"	"	"	1	2	7' 6" 4' 0	"	...	bord and pillar	1	"	450	575	horse	...	...	26/8/80
24	Kowai Pass	"	Lomas, George	"	1½	3	1' 7" 9"	"	E. 1 in 4	bord and pillar	2	"	324	324x	1 hand	...	...	26/8/80
25	Eureka	"	Jackson, T.	"	1	1	1' 6"	"	S.E. 1 in 6	"	2	drive	none	...	4 u. 4 o.	...	...	26/8/80
26	Fern Dale	"	Hamilton, J	"	½	...	...	"	...	...	...	"	784	16,764	3 hand	...	...	27/8/80
27	Canterbury, Sheffield	"	Austin, J	"	18	2	2'	all	S.E. 1 in 3	longwall	1	drive	7,873	19,972	18 u. 2 o.	...	...	13/8/80
28	Homebush, Glentunnel	"	General Manager, Mollraith, J., Mining Manager, Brown, T.	"	8	2	3' and 7'	"	E. 10° S. 1 in 3	bord and pillar	2	"	none	8,000	2 windlass (2)	4"	14"	...
29	Hart's, Malvern	"	Saunders, J	"	...	3	18" 12" and 8"	"	E. 22°	longwall	...	"	"	3,478	engine	12"	5"	...
30	Wallsend	"	"	"	4	3	3' 6"	"	E. 10° S. 1 in 3	"	2	shaft	50	50x	3 hand	...	...	25/1/80
31	Brockley	"	Storey, C.	"	1½	1	3' 6"	"	vertical strike N.E. and S.W.	narrow	...	drive	236	3,236	1	...	...	27/12/79
32	Mount Somers, Mount Somers	"	Milne, James	"	16	1	25'	20'	...	openwork	...	"	40	40x	2 hand	...	...	...
33	Albury, Albury	"	"	"	1	"	5'	"	...	drive	...	"	8	20	6	...	...	...
34	Kakahu, Geraldine	"	Meredith, G., owner	"	½	1	8'	"	...	"	2	shaft	270	5,270	1	...	...	27/9/80
35	Wharekuri, Wharekuri	"	Cairns, W B.,	"	14	1	25'	14'	S. 60° W. very high	narrow work	1	drive	50	50x	1	...	...	27/9/80
36	Kurov, Kurov	"	Scott, D.	"	1	1	"	all	E. 10° S. 1 in 5	bord and pillar	...	"	1,089	2,049x	3	...	...	29/9/80
37	Prince Alfred No. 1, Oamaru	"	Henderson, A.	"	...	2	9'	"	...	"	...	"	2,030	8,955	5 u. 2 o.	...	...	29/9/80
38	Prince Alfred No. 2,	"	Willets, J.	"	4	2	9'	"	"	"	1	"	...	...	...	...	...	...