RETURN of Wrecks and Casualties to Shipping reported to the Marine Department, &c.—continued.

Name of Master.		James Tozer.			W. Dow Wood.	Robert Murdoch.	alter Francis Norbury.	James W. G. Fraser.	Alexander Morrison.	George Roff.
Decision of Court of Inquiry, &c.		Vessel was on her way from Dunedin to Lytel- Jackering the ordinary course, when she struck on a work in a done for Bafara	surds, On a rose, in a curse log. Details casually speed was reduced from eleven to eight and then to four knots an hour. When fog was so dense, master should have directed his course more to the eastward and made more frequent use of the lead. Accident is probably to be attributed to the	presence of a possibly imperceptible but still very strong current. After the vessel struck, extreme order prevailed, and the boats were handled and manned, and the	Ship was being worked into the harbour, when Ship was being worked into the harbour, when she grounded on a shoal through master of the raking sufficient allowance for the state	ttaches to master or crew. The ig run too far to leeward was the misdirection of the semaphore h was made to point in a wrong an accident which arose from the sy of the pilot staff at the New	Current running out of river slewed vessel to Walter Francis northward Norbury.	Casualty caused by striking when crossing the Ja	Loss of ship attributable to error in judgment on part of master in that, after ascertaining his position off Kapiti, he put her on starboard tack, and left her to drift, on chance of picking up the Brothers light, instead of running through Cook Strait. When upon the starboard tack, she went much farther to the westward than he allowed for and	
Wind,	Force.	Light			Light	W.N.W. Moderate	Strong	Moderate	Gale	Moderate
	Direc- tion.	N.W.			N.W.	W.N.W.	W.S.W.	N.W.	N.W.	N.W.
Place where Casualty occurred.		South Head, Akaroa Harbour			Half a mile S, of Ward Island, Wellington Harbour	Point Island, entrance to New River, Inver- cargill	North Spit, Waitara River	Bar of Manawatu River	One mile from Jackson's Head, Port Goro, Cook Strait	Abreast of Waikawau, near Kennedy's Bay, Auckland, about 3 miles off shore
Number of	Lives Lost.	:			:	:	:	:	18	:
Nature of	Casualty.	Stranded; partl. loss			Stranded; nodamage	Stranded; total loss	Stranded: slight	Stranded; rud'r-post	Stranded; total loss	Capsized; partl. loss
	Cargo.	General			Coal	Coal	General	Ballast	General	Timber, logs
Number of	Passen- gers.	15			10	:	H	တ	9	
	Схем.	46			13	<b>L</b> -	G.	12	26	က
ister 18ge,	igeA Tonn	623			519	138	09	21	1143	<b>&amp;</b>
, t	-972 	Schooner			Barque	Brig'ntine 138	Ketch	Schooner	Ship	Schooner
М,	Age and Class.	Ringarooma, s.s., 9 years			Genevieve M. Tucker, 14 years	Augusta, 13 years		Jane Douglas, s.s., 9 years	Lastingham, 7 years	Norah, 11 months
Date of Casualty.		1884. Aug. 16			, 23	24	, 29	08 *	Sept. 1	27