

Name of Dredge.	Owners.	Dredgemaster.	Remarks.	Dates of Visits.
<i>CLUTHA RIVER—continued.</i> Gold-deposit, Coal Creek Flat ..	Gold-deposit Gold-dredging Company	J. Guyton S. Coard ..	Ready to start; only one boat provided Platform required around tailings-chute; light-lines and boat-hooks required; also runner on the boat-line and a gangway across the well. Company was notified on 15th October, 1901, that the second boat was unfit for river-work. Dredge on the point of closing down owing to high river	21/8/01. 11/10/01.
Long Valley, Coal Creek Flat ..	Long Valley Gold-dredging Company	W. Woodhouse	One buoy required; main and pump driving-belts to be fenced off Belts not fenced; elevator is being replaced by stone-chute ..	19/7/01. 11/10/01.
<i>Coal Creek—Alexandra Gorge</i> (<i>Clutha River</i>). Sixteen-mile Beach ..	Sixteen-mile Beach Gold-dredging Company	R. F. Kitto	Shifting to the claim; regulations not posted; otherwise in good order. This dredge has since been wrecked, and almost entirely lost, on 29th October, 1901, only the engines being recovered	1/6/01.
Fourteen-mile Beach ..	Fourteen-mile Beach Gold-dredging Company	G. P. Blue	Boat-hook in boat too short; otherwise dredge and appliances in good order ..	3/6/01.
Golden River ..	Golden River Gold-dredging Company	G. Taylor	Getting ready to start .. Hatchway to be cut aft for access to pump; screen driving-belt to be guarded, also the main and pump driving-belts; boats to be provided with life-saving apparatus	23/7/01. 20/8/01.
Golden Falls River Molyneux ..	Golden Falls Gold-dredging Company River Molyneux Gold-dredging Com- pany	S. Hoy .. C. Weaver	Screen driving-belt not yet fenced .. Shifting down river to claim. Company notified second boat unsuitable for river-work .. Ready to drop down the river six miles to the claim. Found dredge not well equipped with life-saving apparatus, and had her properly equipped before starting; hatchway to be cut for access behind the pump	10/10/01. 3/6/01. 22/7/01.
First Chance ..	First Chance Gold-dredging Company	A. McLean	Dredge and appliances in good order .. Dropping down river to claim; dredge well equipped .. Pump-belt and main rope-drive require fencing ..	19/8/01. 3/6/01. 22/7/01.
Bendigo ..	Bendigo Gold-dredging Company ..	T. McMath	Dredge and life-saving appliances in good order. A. McLean, dredgemaster, fell overboard on 3rd October, 1901, and was drowned	5/10/01.
Sailor's Bend ..	Sailor's Bend Gold-dredging Company	J. Dewar ..	Shifting to claim; boats equipped and dredge furnished with life-saving apparatus Forward railing weak; runner required to replace shackle on coal-boat line; fence-bar required across side opening	20/8/01. 7/10/01.
Manuherikia ..	Manuherikia Gold-dredging Company	L. Anderson	Sleeve required on projecting end of engine-shaft .. Dredge and appliances in first-class order, and regulations observed ..	3/6/01. 7/10/01.
Moa ..	Clyde Dredging Company ..	W. Nicholson	Main driving-belt requires to be fenced .. Dredge and appliances in excellent order, and regulations observed .. Repairing on this date ..	3/6/01. 8/10/01. 3/6/01.
<i>Alexandra.</i> Molyneux Hydraulic ..	Molyneux Hydraulic Gold-dredging Company	C. Simonsen	Dredge and appliances in fair order; second boat laid up for repairs ..	8/10/01.
Alexandra Eureka ..	Alexandra Eureka Gold-dredging Com- pany	N. Bradley	Regulations not posted; light-lines and boat-hooks not in place .. Dredge and appliances in good order ..	6/6/01. 9/10/01.
Golden Beach ..	Golden Beach Gold-dredging Company	J. Percy ..	Dredge repairing, but appliances in good order .. Sleeve required on engine-shaft; elevator driving-belt requires fencing ..	8/10/01. 4/6/01.
Ngapara No. 1 ..	Ngapara Gold-dredging Company ..	A. Schumann	Light-lines under required length .. Dredge and appliances in fair order ..	8/10/01. 6/6/01.
Enterprise No. 1 ..	Enterprise Gold-dredging Company ..	J. T. Ryan	Repairing, but all in good order .. Regulations not posted; life-saving apparatus requires renewal ..	9/10/01. 6/6/01.
Enterprise No. 2 ..	Enterprise Gold-dredging Company ..	G. MacGregor	One life-belt useless; otherwise in good order .. Sleeve required on engine-shaft; life-saving apparatus not in good condition .. Undergoing repairs ..	9/10/01. 22/7/01. 9/10/01.