

WORKING DREDGES INSPECTED—continued.

Name of Dredge.	Owners.	Dredgemaster.	Remarks.	Dates of Visits.
CARDRONA VALLEY. Lone Star, below Branch Creek	Lone Star Gold-dredging Company ..	C. Melton	Heaving-lines required; well-hole fencing down; forward and well-hole gangways not in position; main belts not fenced; boat not in paddock	14/7/02.
La Franchi's ..	La Franchi's Gold-dredging Company	A. La Franchi	Dredge and life-saving appliances in fair order. ..	20/10/02.
Nevis River.			Boat-hooks and heaving-lines required; guard screen, driving-gear, and all set-screws; forward and well-hole gangways required	14/7/02.
Crewe ..	Crewe Gold-dredging Company ..	J. A. Cheshire	Dredge and life-saving appliances in fair order; heaving-lines required ..	20/10/02.
Carriek ..	Carriek Gold-dredging Company ..	J. Thompson	Fencing required on stern and bows; main belts and screen driving-gear not guarded; regulations not posted	31/10/02.
New Nevis ..	New Nevis Gold-dredging Company	J. Thompson	Contractors removing dredge to Upper Nevis ..	31/10/02.
Ngapara No. 2 ..	Ngapara Gold-dredging Company ..	A. McLean	Guard winch bevel gear and main and elevator driving-belts; boat-hooks and heaving-lines required; new copy of regulations to be posted up	31/10/02.
Ngapara No. 3 ..	Ngapara Gold-dredging Company ..		Heaving-lines and boat-hooks required; otherwise life-saving appliances in good order	31/10/02.
Nevis Crossing ..	Nevis Crossing Gold-dredging Company		Fence bows; guard rope-drive and pump-belt; bar required across the coal-door ..	31/10/02.
BANNOCKBURN.			Contractors removing Remarkables dredge to the Nevis Crossing ..	31/10/02.
Shepherd's Creek ..	Shepherd's Creek Gold-dredging Company	Position vacant	Dredge standing for some considerable time ..	14/7/02.
MANUHERIKIA RIVER.				
Golden Link, Alexandra ..	Golden Link Gold-dredging Company	W. Poulter	Well-hole fencing to be erected; heaving-lines and boat-hooks required; this dredge requires to be provided with a second boat	8/2/02.
Morning Star, above Alexandra	Morning Star Gold-dredging Company	W. Mason	Forward gangway not in position; two buoys, 150 ft. of heaving-line, and two boat-hooks required	11/2/02.
Olrig, Springvale ..	Olrig Gold-dredging Company ..	J. Timmings	Boat-hooks and heaving-lines required; new copy of regulations to be posted up ..	11/10/02.
Ida Valley.		E. A. Johnston	Dredge and life-saving appliances in good order ..	8/11/02.
Cairntrodlie Poolburn	Cairntrodlie Gold-dredging Company	H. Mercer	Elevator driving-gear to be guarded; forward railing to be erected ..	11/2/02.
NASEBY.			Boat not in paddock; otherwise dredge and life-saving appliances in good order ..	19/2/02.
Roberts's Naumai, Upper Kye-burn	E. Roberts ..	C. McQueen	Heaving lines required; boat not in paddock ..	5/12/02.
Evans Flat, Evans Flat	Evans Flat Gold-dredging Company	T. Gillespie	Dredge and life-saving appliances in fair order ..	12/12/02.
Lawrence, Tuapeka Flat	Lawrence Gold-dredging Company ..	S. McStay	Light-lines and boat-hooks required; main belts and fly-wheel to be guarded; regulations not posted	19/6/02.
Reliance, Tuapeka Flat	Reliance Gold-dredging Company ..	J. Hughes	Boat not equipped; life-buoys to be re-covered; boat-hooks and light-lines to be provided ..	19/6/02.
Tuapeka, Tuapeka ..	Tuapeka Gold-dredging Company ..	R. Montgomery	Two boat-hooks and 150 ft. of heaving-line required; forward gangway not in position; bevel gear and fly-wheel to be guarded	19/6/02.
Gabriel, Tuapeka Flat	Gabriel Gold-dredging Company ..	J. P. Uren	One boat-hook missing; boat not equipped; stern railing down..	19/6/02.
Happy Valley, Wetherstone's	Happy Valley Gold-dredging Company	A. N. Wakefield	One boat-hook required; boat not equipped ..	19/6/02.
Golden Rise, Wetherstone's ..	Adams, Smythe, and party ..	J. Buchanan	Guard fly-wheel, set-screws on winch-shaft, also main and pump driving-belts; well-hole and forward gangways not in use	21/8/02.
			Dredge and life-saving appliances in fair order ..	21/8/02.