Working Dredges inspected-continued.

Name of Dredge.	Owners.	Dredgemaster.	Remarks.	Visits.
TUAPEKA—continued. Imperial, Waitahuna	Imperial Gold-dredging Company	W. Noble	Outside guard required on the top gearing; beaving-lines and boat-hooks required; new	22/8/02.
Havelock, Waitahupa	Havelock Gold-dredging Company	W. Rowe	required; ny-wheel to be guarded. 1g-lines required; set-screws on winch-shaft to be guarded; n	22/8/02.
Gordon, Waitabuna	Gordon Gold-dredging Company	H. Crozier	regulations required Well-hole gangway required; outside guard required on the top gear; boat to be equipped	22/8/02.
Manuka, Waitahuna	A. C. Broad	J. Baker	With life-taying apparatus Forward and well-hole gangways not in use; boat-hooks and heaving-lines required;	22/8/02.
Waitahuna Gully, Waitahuna	Waitahuna Gold-dredging Company	J. Donaldson	regulations not posted Fly-wheel and main belts to be fenced; set-screws on winch-shaft to be guarded; boat- hote remined to be to commend with life sering concentre; regulations not noted	22/8/02.
GLENÖRE. Gold Bank, Glenore Stirling, Glenore	Gold Bank Gold dredging Company Stirling Gold-dredging Company	W. Thomas	Dredge standing; new pontoons to be built	22/8/02. 22/8/02.
WALPOBL. New Jutland Flat, Waipori	New Julland Flat Gold-dredging Company	Not appointed T. Jefferson	This dredge is being fitted with O'Brien's system of hydraulic power Guard required on top gear; set-screws to be guarded; well-hole gangway required	19/4/02. 18/8/02.
O'Brien's Patent, Waipori	Quilter and party	W. Quilter	Dredge and life-saving appliances in good order Re-erecting the dredge at Waipori Township Yisited in connection with the accident on the 13th August, 1902. W. Quilter, winchman, while ciling monthings in motion had his own the connection with the second and the connection of the	27/11/02. 6/3/02. 16/8/02.
Upper Waipori, Waipori	Upper Waipori Gold-dredging Com-	C. Haggitt	Dredge and life-saving appliances in fair order	27/11/02. 18/4/02.
Waipori Consolidated, Waipori	pany Waipori Consolidated Gold-dredging	T. Jefferson	Forward gangway to be repaired	6/3/02.
Success, Waipori	Company Success Gold-dredging Company	W. Hanley	Two buoys to be re-covered Dredge visited in connection with drowning fatality on 30th January, 1902. J. J. McClusky was drowned through swamping of the host while under-tunning a line	18/4/02. 31/1/02.
Perseverance (McNeil's), Waipori Empire No. 1, Waipori	Perseverance (McNeil's), Waipori Perseverance Gold-dredging Company Empire No. 1, Waipori Empire Gold-dredging Company	D. Aitken G. Larkins	Dredge and life-saving appliances in good order One buoy to be re-covered; 150 ft. of heaving-lines and two boat-hooks required; sleeve to	18/4/02. 18/4/02. 18/4/02.
Golden Shore, Waipori	Golden Shore Gold-dredging Company	R. Allen	be put on main engine-snait Dredge and life-saving appliances in good order	18/4/02. $28/11/02$.
Empire No. 2, Waipori	Empire Gold-dredging Company	G. Larkins	One boat - hook missing; sleeve required on main engine shaft; forward gangway out of	17/4/02
Lower Enfield, Waipori	Lower Enfield Gold-dredging Company	C. Potts	Dredge and life-saving appliances in good order This dredge is being fitted with O'Brien's system of hydraulic power New dredge not yet equipped with life-saving appliances, nor machinery efficiently guarded	28/11/02. 17/4/02. 17/8/02.
Enfield, Waipori Big Fist, Verterburn Broad Creek, Welch's Flat	Enfield Gold-dredging Company Big Flat Gold-dredging Company Broad Creek Gold-dredging Company	C. Adamson Caretaker D. Mitchell	Fence the bows and guard winch bevel gear; forward gangway required Screen driving-gear and winch-pinions to be guarded; bows to be fenced in Dredge standing New dredge not yet equipped with life-saving appliances, nor machinery efficiently guarded	28/11/02. 17/4/02. 17/4/02. 17/4/02.