

WORKING DREDGES INSPECTED—continued.

Name of Dredge.	Owners.	Dredgemaster.	Remarks.	Dates of Visits.
WAIMUMU STREAM, WAIMUMU.				
Victoria, Waimumu ..	Victoria Waimumu Gold-dredging Company	H. Quettier	Dredge ready to start work ..	22/1/02.
Treasure, Waimumu ..	Private ..	F. Browne	Dredge being dismantled for removal to Waikaka ..	26/8/02.
		W. F. Thompson	Dredge standing ..	22/1/02.
			This dredge has not yet been efficiently provided with life-saving appliances, nor the machinery properly guarded ..	26/8/03.
Waimumu Queen ..	Waimumu Queen Gold-dredging Company	Ed. Reid ..	Forward gangway required; dredge repairing ..	22/1/02.
		J. Murray	Dredge undergoing extensive overhaul ..	26/8/02.
Waimumu Extended ..	Waimumu Extended Gold-dredging Company	G. Pettigrew	Dredge and life-saving appliances in good order ..	22/1/02.
		H. Leicester	Well-hole gangway to be provided; pulley on main engine to be guarded ..	26/8/02.
Waimumu ..	Waimumu Gold-dredging Company ..	J. F. T. Berendsen	One buoy missing; dredge repairing ..	22/1/02.
			Dredge and life-saving appliances in fair order; recommended a passage-way to be made under the tables ..	26/8/02.
Royal Waimumu ..	Royal Waimumu Gold-dredging Company	W. Wilson	New dredge not provided with life-saving appliances, nor machinery efficiently guarded ..	22/1/02.
			Rules not posted; forward gangway not in position; guard set-screw and coupling on winch driving-shaft ..	26/8/02.
Waimumu Central ..	Waimumu Central Gold-dredging Company	D. Caithness	Well-hole and forward gangways not provided; 150 ft. of heaving-line required ..	22/1/02.
Burrell's Freehold ..	Burrell's Freehold Gold-dredging Company	G. Bennett	Well-hole gangway required; otherwise dredge and life-saving appliances in good order ..	26/8/02.
McLean's Freehold ..	McLean's Freehold Gold-dredging Company	D. McKenzie	Dredge and life-saving appliances in good order ..	22/1/02.
CHARLTON CREEK, CHARLTON.				
MacCharlton ..	MacCharlton Gold-dredging Company	P. Brandt	Re-erecting Milestone dredge ..	22/1/02.
			Well-hole gangway required; hatch to be cut for easy access behind the pump; bevel gear to be guarded; boat not yet provided ..	26/8/02.
Charlton Creek ..	Charlton Creek Gold-dredging Company	C. Bennett	New dredge not yet equipped with life-saving appliances ..	27/8/02.
			Fly-wheel of main engine and pump-belt to be fenced; forward gangway not in position ..	1/9/02.
Central Charlton ..	Central Charlton Gold-dredging Company	J. McCorkindale	Dredge and life-saving appliances in good order ..	23/1/02.
Charlton Valley ..	Charlton Valley Gold-dredging Company	W. G. Mouat	Boat not in paddock; one buoy not on bows; boat-hook and light-line required aft ..	27/8/02.
		W. McCorkindale ..	Dredge and appliances in fair order ..	23/1/02.
			Well-hole gangway not in position; bar required across coal-door; fly-wheel to be guarded; one boat-hook and 50 ft. of heaving-line required ..	27/8/02.
Lady Charlton ..	Lady Charlton Gold-dredging Company	J. Murray	Dredge and life-saving appliances in good order ..	24/1/02.
		W. Gibb ..	Dredge standing ..	27/8/02.
WAIKAI RIVER.				
Mystery Flat, Waikaita ..	Mystery Flat Gold-dredging Company	E. Lawson	Forward gangway required ..	10/5/02.
Nugget, Upper Waikaita ..	Private syndicate ..	J. Taylor ..	Dredge and life-saving appliances in fair order ..	11/5/02.
Muddy Creek (Limited), Muddy Creek	Muddy Creek Gold-dredging Company (Limited).	F. Browne	" ..	12/5/02.
WAIATU RIVER.				
Belmont, Clifton ..	F. Jack ..	D. O'Leary	Second boat not at the dredge; railing torn off bows ..	24/4/02.
			Visited dredge in connection with the fatal accident on 28th July, 1902. While boating wood Charles Prince was drowned through boat swamping ..	30/7/02.