

ACCIDENTS IN FACTORIES, ETC., REPORTED DURING THE YEAR 1906-7—*continued.*

Trade or Industry.	Locality.	Killed.	Injured.	Nature of Injury.	Cause.
CANTERBURY INDUSTRIAL DISTRICT—<i>continued.</i>					
Carpentering and joinery— Apprentice	Oxford	1	1	Lost part all fingers and thumb of right hand	Caught in planing-machine.
Carpenter	Timaru	1	1	Lost finger ..	Caught on saw.
Various		4	4	Slight cuts, bruises, &c.	
Meat-freezing, &c.— Labourer	Pareora	1	1	Skull fractured ..	Struck by belting.
Fellmonger		1	1	Lost part of finger ..	Caught in cutting-machine.
Greaser		1	1	Foot badly injured ..	Rusty nail ran into it.
Butcher		1	1	Lost part of finger ..	Blood-poisoning following cut.
Labourer		1	1	Arm and shoulder badly cut ..	Caught on shafting.
Various		3	3	Slight cuts, bruises, &c.	
Oatmeal-milling— Various	Christchurch	2	2	Slight cuts, bruises, &c.	
Sawmilling— Sawyer	Waimate	1	1	Lost two fingers ..	Cut on circular saw.
Various	Christchurch	1	1	Lost part of one finger	
.. .. .		4	4	Slight cuts, bruises, &c.	
OTAGO AND SOUTHLAND INDUSTRIAL DISTRICT.					
Biscuit-manufacturing, confectionery, &c.— Packing-room hand ..	Dunedin	1	1	Leg broken ..	Carried round shafting.
Biscuit-maker		1	1	Arm crushed ..	Caught in rollers of dough-machine.
Confectioner		1	1	Hand crushed ..	Ditto.
Various		5	5	Hand badly burned ..	Put it into boiling toffee.
Boxmaking— Various	Dunedin	5	5	Slight cuts, burns, bruises, &c.	
Cabinetmaking— Apprentice		1	1	Slight cuts, bruises, &c.	
Cabinetmaker		1	1	Poisoned hand ..	Bruised by piece of timber.
Apprentice		1	1	Lost finger ..	Caught in circular saw.
Machinist		1	1	Hand and wrist badly torn	Caught on bit of boxing-machine.
Assistant		1	1	Hand badly cut ..	Caught on circular saw.
Various		6	6	Lost two fingers ..	Caught in planing-machine.
Carpentering, joinery, &c.— Carpenter	Oamaru	1	1	Slight cuts, bruises, &c.	
Labourer	Dunedin	1	1	Lost four fingers ..	Caught in planing-machine.
Joiner		1	1	Arm broken ..	Fell from ladder.
Various		1	1	Broken shoulder ..	Fell down stairs.
Cement-works— Labourer		1	1	Lost finger; hand torn	Caught in planing-machine.
Quarryman		1	1	Slight cuts, bruises, &c.	
Engineering— Dresser		1	1		Inhaled poisonous fumes.
Engineer		1	1	Poisoned ..	Fell over face of quarry.
Coppersmith		1	1	Serious abdominal injuries	Bursting of emery wheel.
Apprentice		1	1	Lost part of finger ..	Jammed in shafting.
Rangemaker		1	1	Crushed thumb ..	Caught in rollers of corrugating-machine.
Apprentice		1	1	Lost part of finger, three fingers crushed	Casting fell on it.
Engineer		1	1	Thumb crushed ..	
Blacksmith		1	1	Severe injury to face ..	Caught in cog-wheels.
Boilermaker		1	1	Ankle broken ..	Piece of steel struck him.
Machinist		1	1	Leg broken ..	Horse trod on him.
Boilermaker		1	1	Lost finger ..	Iron plates fell on him.
Various		60	60	Lost finger ..	Caught in cog-wheels.
Gas-manufacturing— Yardman		1	1	Two fingers crushed ..	Piece of iron struck him.
Stoker		1	1	Slight cuts, bruises, &c.	
.. .. .		1	1		Fell, causing intestinal strangulation.
.. .. .		1	1	Concussion of brain ..	Fell down lift.
.. .. .		1	1	Severe abdominal injuries	Ran up against handle of wheelbarrow.
.. .. .		1	1	Sprained ankle and cut face	Fell down stairs.
Various		7	7	Slight cuts, bruises, &c.	
Brickmaking— Brickmaker	Mosgiel	1	1	Lost part of three fingers	Caught in brick press.
Labourer	Milton	1	1	Bruised arm and side ..	Fell over bank.
.. .. .	Invercargill	1	1	Leg badly bruised ..	Crushed between hopper and box.
.. .. .		1	1	Lost part of finger ..	Caught in brick-press.
Boot and shoe manufacturing— Various	Dunedin	2	2	Slight cuts.	
Brushmaking— Machinist		1	1	Lost two fingers and part of hand	Caught in brush-shaping machine.
Printing, &c.— Various		3	3	Slight cuts.	