

No. 3.—RETURN of NOTICES given to REPAIR BOILERS—*continued.*

Number.	Type.	Description of Repairs.
2	Multitubular	Compensating-rings fitted round mudhole-openings and new doors fitted.
2	"	Crown-plates of steam-dome patched.
1	"	Crown-plate of steam-dome renewed.
1	"	Defective patch taken off shell and a larger one fitted.
1	"	Defective plates repaired.
1	"	Defective rivets in circumferential seams renewed.
1	"	Eight rivets in bottom of tube-plate renewed.
1	"	Fifteen new rivets put in circumferential seams.
1	"	Five new tubes fitted.
1	"	Four new stay-tubes fitted.
1	"	Large patch fitted on the bottom of front tube-plate.
1	"	Manhole and mudhole openings fitted with compensating-rings.
2	"	Manhole-door dogs repaired.
4	"	Manhole-doors repaired.
2	"	Manhole-door spigots riveted.
1	"	Manhole-opening riveted.
3	"	Mudhole-doors repaired.
1	"	New bottom-plate fitted in shell.
3	"	New manhole-doors.
1	"	New manhole-door, new mudhole-door, and compensating-ring round manhole-opening riveted.
1	"	New mud-drum fitted.
6	"	New mudhole-doors.
1	"	New studs fitted in mud-doors.
2	"	One new longitudinal stay.
2	"	One new rivet put in shell.
1	"	One new rivet put in back tube-plate.
1	"	One new stay-tube fitted.
6	"	One new tube fitted.
1	"	Part of shell renewed.
1	"	Patch fitted on back tube-plate.
2	"	Patches fitted on crown of steam-dome.
1	"	Patch fitted on front tube-plate.
1	"	Patch fitted on shell under check-valve.
1	"	Patch fitted on shell under check-valve, and patch where sling-stay goes through crown of boiler.
1	"	Patch fitted under main stop-valve chest.
1	"	Patches on bottom of shell rejoined.
1	"	Plate cut out of bottom, and new one fitted.
1	"	Plug fitted in front tube-plate for cleaning.
14	"	Retubed.
1	"	Retubed, and new mudhole-door fitted.
2	"	Several new tubes fitted.
1	"	Several new tubes, and new mudhole-door fitted.
6	"	Several tubes expanded.
3	"	Ten new tubes fitted.
1	"	Three new rivets in manhole-door.
1	"	Three new tubes fitted.
2	"	Top row of tubes expanded.
1	"	Two new manhole-doors, compensating-rings round manhole-openings, patch on crown of steam-dome, and patch on back tube-plate fitted.
1	"	Two new plates fitted in bottom of shell.
1	"	Two new tubes fitted.
12	Portable	A number of new screwed stays fitted in sides of firebox.
1	"	A number of new screwed stays fitted in sides of firebox, and a patch on crown of firebox.
1	"	A number of new screwed stays fitted in sides of firebox, and new girder-stays.
1	"	All crown-stays in firebox renewed.
1	"	Bottom of firebox repaired.
28	"	Compensating-rings fitted to mudhole-openings.
1	"	Compensating-rings fitted to mudhole-openings, and three new tubes put in.
4	"	Compensating-rings fitted to mudhole-openings, and two new studs in mud-doors.
1	"	Compensating-rings fitted to mudhole-openings, two new screwed stays in firebox, and one new longitudinal stay.