No. 17.—Return of Vessels surveyed for Seaworthiness—continued.

of Survey.	Name of Vessei.	Where surv	eyed.	Nature of Casualty, &c.
1907. June 26	S.s. Nora Niven .	. Dunedin .	• •	This vessel was steaming up to Dunedin or the night of the 25th June, and, when in the upper harbour, she got out of the channe
July 6, 8, 9	" fndra	. Auckland .	•	and touched the sand-bank. An inspection was made of the hull, when the vessel was found to have sustained no damage. It was found necessary, while on a voyage from Valparaiso to Sydney, to put into Auck land on the 6th July for repairs to machinery and for coal. The vessel was docked, and the stern length of shafting drawn; and
July 6, 8, 9,	" Rakaia .	. Auckland .	• . ••	the stern-bush was relined to the satisfaction of the surveyor.  After this vessel's arrival in Auckland from London, the machinery was being over hauled, when, on the 1st July, a fracture of a serious nature was discovered in the M.P. crank-shaft, necessitating its removal A spare shaft which was on board the vesse
July 10	" Penguin	. Wellington .		was fitted in its place.  Whilst entering Nelson Harbour at 5.15 a.m on the 9th July, after a voyage from Picton the vessel grazed the rocks near the leading beacons with her starboard bilge. On he return to Wellington, on the 10th July, a diver examined the ship's bottom, and a surveyor made an internal examination. It was found that the ship had received no
July 25	" Te Anau .	. Dunedin .		damage.  This vessel was entering Nelson Harbour of the 16th July, after a voyage from Welling ton, when she stranded on a shingle-band alongside the wharf, through the flood-tide sheering her into shallow water. She remained there from 10.20 a.m. till 11.5 a.m. when she came off with her own power On her arrival in Dunedin a survey was made, and the vessel was found to have
July 26	" Kaiapoi	. Lyttelton		received no damage.  Whilst the vessel was being shifted in Sydney Harbour on the 26th June by a tug-boat the propeller came in contact with the wharf-piles, breaking one of the blades Upon the vessel's arrival in Lyttelton she was placed in the dry-dock, the propeller shaft drawn and examined, and a new
July 27	Ilma (barquentine)	. Kopu, Thames	·	propeller fitted.  This vessel left Gisborne for Kopu on the 10tl July in tow of the steamers "Tawera" an "Nautilus." At the end of the breakwater the vessel sagged to leeward, as the tugs were no powerful enough, in the fresh southerly galwhich was blowing, to prevent this. The vessel was dragged on to the breakwater striking slightly amidships. It was though that no damage had been done, so the vesse proceeded on her voyage. The following
	,			morning there was a considerable depth o water in the hold. Upon examination, is leak was discovered, which was temporarily repaired to enable the vessel to complete here voyage to Kopu, Thames, where repair
Aug. 5	S.s. Tarawera	Dunedin .		were effected.  The owners of this vessel desired to change her certificate from home trade to foreign going. The boats, rafts, and other equip ments were inspected, the necessary additions made, and the required number of officers supplied to comply with the Shipping
Aug. 6	" Maheno	, Dunedin		and Seamen Act.  Whilst on a voyage from Lyttelton to Dunedio on the 2nd August, the centre stern-tub was found to be cracked circumferentiall about two-thirds round. Temporary repair were effected in Dunedin by fitting a clam round the tube; the vessel was thus enabled.
Aug. 7	" Arahura	. Nelson		to proceed to Lyttelton for docking, wher permanent repairs were effected.  While the vessel was on a voyage from Westpor to Nelson she lost her port propeller abou 1 a.m. on the 7th August, when seventy-eigh miles from Westport. Having twin screw she proceeded on her voyage to Nelson with the starboard engine. There a survey wa made, and the vessel allowed to proceed to