No. 3.—RETURN of Notices given to REPAIR Boilers—continued.

Number.	Туре.	Description of Repairs.
1	Portable	Two rows of screwed stays renewed in firebox.
: 1	·,	Two rows of screwed stays renewed in throat-plate.
1		Wasted part of foundation-ring patched.
1	Semi-portable	Four new screwed stays fitted in firebox.
$\overset{1}{2}$	**	One new longitudinal stay fitted Patches fitted in firebox.
ī	••	Retubed.
1	Semi-tubular	New compensating-ring fitted to manhole-opening.
1	,,	New dog and stud fitted to mud-door.
1	***	New studs fitted in mud-door.
2 5	14	Patches renewed Retubed.
ĺ	••	Several new nuts fitted on stay-tubes.
1	***	Several new screwed stays fitted in furnace.
1	. **	Two new grider-stays fitted.
l	(Dana adding)	Two new pins in longitudinal stays.
6	Traction	A number of new screwed stays fitted in firebox. Compensating-rings fitted to manhole-openings.
i I	•••	Compensating-ring fitted to manhole-opening, and seven new tubes
	,,	fitted.
1	**	Compensating-rings fitted to mudhole-openings.
1	,.	Coupling-pins in longitudinal stays renewed.
1		Cracks in side of firebox chain-pinned.
1 	* **	Eighteen new screwed stays fitted in firebox Firebox-crown repaired.
· • i	• • • • • • • • • • • • • • • • • • • •	Five new screwed stays fitted in throat-plate.
1	,,,	Five new tubes fitted.
1	,,	New dogs fitted to manhole-door.
2	· ,.	New firebox fitted.
ì	,•	New firebox fitted, three new stay-tubes and new coupling-pins in longitudinal stays.
2		New mud-doors fitted.
$\frac{7}{2}$.,	New studs fitted in manhole-door.
1	: ••	One new girder-stay fitted.
1	***	Patch fitted on crown of firebox.
3	;•	Patches fitted in firebox.
Same of the	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	Patches fitted on foundation-ring Patch fitted on shell under blow-off cock.
i	i ,,	Plughole retapped, and new tapered plug fitted.
10	, ,,	Retubed.
$\frac{2}{1}$,,	Retubed, and new fireboxes fitted.
1	•••	Retubed, and new studs fitted in manhole-door Retubed, and new firebox-crown fitted.
$\frac{2}{1}$		Retubed, thirty-six new screwed stays fitted in firebox, new studs in
-	! ** :	manhole-door, and compensating-ring fitted round manhole-open-
		ing.
1	,,	Seven new tubes and four new screwed stays fitted in firebox.
3	. "	Several new screwed stays fitted in firebox.
1	**	Several new tubes fitted Sixteen new screwed stays fitted in firebox.
i	,,	Ten new tubes fitted.
2		Tubes expanded.
1	.,	Tubes in firebox-end expanded.
1	3 1	Twenty-four new screwed stays fitted in firebox.
$rac{1}{2}$	Vertical cross-tu	A row of new screwed stays fitted round firebox. Angle-collar renewed round uptake.
ĺ	••	Compensating-ring fitted round manhole-opening.
5	,,	Compensating-rings fitted round mudhole-openings.
1	••	Compensating-ring fitted round mudhole-opening, and new collar
•	II	round uptake.
1	•	Manhole-door repaired.
$\frac{2}{4}$,•	New manhole-doors fitted. New mudhole-doors fitted.
1		New spigot fitted to manhole-door.
1		New studs fitted to mudhole-door.
1		
1 1 1	,,	New vertical stays fitted. Patches fitted in firebox.