

No. 3.—RETURN OF NOTICES GIVEN TO REPAIR BOILERS, ETC.—*continued.*

Number.	Type.	Description of Repairs.
3	Multitubular	.. New studs fitted to mudhole-doors.
2	"	.. Patch fitted on bottom of shell.
1	"	.. Patch fitted on bottom of shell, and several new tubes.
1	"	.. Patch fitted on bottom of shell over cracked rivet-holes and grooving.
1	"	.. Patch fitted on bottom of shell over wasted landings.
1	"	.. Patch riveted over circumferential seams where cracked.
6	"	.. Patches riveted over wasted portions of bottom.
2	"	.. Patches taken off bottom of shell, and extended ones fitted.
1	"	.. Patches under mountings renewed.
9	"	.. Retubed.
1	"	.. Retubed, and compensating-rings fitted to mudhole-openings.
1	"	.. Retubed, compensating-ring fitted to mudhole-opening, and two new longitudinal stays in steam-space.
1	"	.. Retubed, patch fitted on shell under check-valve, and new spigot to manhole-door.
1	"	.. Several rivets renewed in shell.
1	"	.. Several rivets renewed in steam-dome.
5	"	.. Several tubes renewed.
1	"	.. Sixteen new tubes fitted.
1	"	.. Sixteen tubes drawn to clean boiler, and tubes afterwards renewed.
1	"	.. Ten rivets renewed in steam-dome and sixteen in shell.
1	"	.. Top row of tubes renewed.
2	Portable	.. A number of new screwed stays fitted in sides of firebox.
1	"	.. All new screwed stays fitted in firebox.
1	"	.. Compensating-ring fitted to manhole-opening.
22	"	.. Compensating-rings fitted to mudhole-openings.
1	"	.. Compensating-rings fitted to mudhole-openings, and new dogs for mud-doors.
1	"	.. Compensating-rings fitted to mudhole-openings, and several new tubes fitted.
1	"	.. Corners of firebox repaired.
1	"	.. Eight new screwed stays fitted in firebox.
1	"	.. Eighteen new screwed stays fitted in firebox.
1	"	.. Eleven new screwed stays fitted in firebox.
1	"	.. Eleven new tubes fitted.
1	"	.. Fifteen new screwed stays fitted in firebox.
1	"	.. Fifteen new screwed stays fitted in firebox, and compensating-ring to mudhole-opening.
1	"	.. Forty-eight new screwed stays fitted in firebox.
1	"	.. Foundation-rings repaired.
1	"	.. Fourteen new screwed stays fitted in firebox.
1	"	.. Girders and stays renewed on firebox-crown, and compensating-rings fitted to mudhole-openings.
1	"	.. Girder-stays renewed.
1	"	.. New firebox and several patches on outer shell fitted.
1	"	.. New girders fitted on crown of firebox.
1	"	.. New girders fitted on crown of firebox, and several new stays fitted.
1	"	.. New manhole-door fitted.
6	"	.. New mudhole-doors fitted.
2	"	.. New mudhole-doors fitted and openings dressed out.
1	"	.. Nine new tubes fitted.
1	"	.. Nine new tubes fitted.
1	"	.. One new cross-girder with three stays fitted to crown of firebox.
1	"	.. One new longitudinal stay fitted.
1	"	.. Patch fitted on firebox-crown, and four new screwed stays.
1	"	.. Patch fitted on firebox-crown, and six new rivets put in front tube-plate.
1	"	.. Patch fitted on side of firebox, and six new screwed stays.
2	"	.. Patches on crown of firebox renewed.
1	"	.. Patches on foundation-ring renewed, nine new tubes and one new mud-door fitted.
1	"	.. Patch put on shell under feed-pump, and mudhole-opening compensated.
6	"	.. Retubed.
1	"	.. Retubed, and new tube-plate fitted.
1	"	.. Retubed, and twenty new screwed stays fitted in firebox.
1	"	.. Retubed, mudhole-opening compensated, and new mud-door.