

Plan of Portion of Ralph's Mine, Huntly, N.Z. October, 1914.

—REFERENCE—

Intake airways shewn thus

Falls " "


Return-air scaling (approx.) " "

Short-circuited air-current " "


Isolated panel " "

Direction of force " "

Positions and reference-numbers of bodies " "




X 43



A List of those Killed in the Explosion at
Ralph's Colliery, Huntly, 12th September,
1914.

Plan No.	Name.	Rank.
1	John Whorskey ..	Deputy.
2	Samuel Jackson ..	Shiftman.
3	John Skellern ..	Deputy.
4	William Burt ..	Shiftman.
5	John Robinson ..	
6	William Hinchco ..	
7	Henry Peckham (senr.) ..	Deputy.
8	Jacob Thompson ..	Horse-driver.
9	James Holden ..	Shiftman.
10	Charles Maloney ..	Trucker.
11	William Blaven ..	
12	Robert Munie ..	Shiftman.
13	James Darby ..	Deputy.
14	William Kelly ..	Contractor.
15	Daniel Lyons ..	Shiftman.
16	Hutchinson Burt ..	Trucker.
17	John Steele ..	Roadman.
18	David Patterson ..	
19	William Patterson ..	Contractor.
20	Alexander Izatt ..	Ropeboy.
21	John Bowler ..	Trucker.
22	William Mayland ..	Clipper.
23	William Dixon (or Mitchell) ..	Trucker.
24	Fred Taylor ..	
25	Thomas Casson ..	
26	Theophilus Molesworth ..	Winchman.
27	Arthur Ruston ..	Roadman.
28	Henry Jackson ..	Clipper.
29	William Roper ..	Trucker.
30	William Allen ..	Clipper.
31	William Smith ..	Deputy.
32	William Burton ..	Trucker.
33	John Greener ..	Shiftman.
34	William Gowans ..	Temporary Manager.
35	William Brocklebank (senr.) ..	Shiftman.
36	Seymour Hopper ..	Trucker.
37	William Blenkinsopp ..	Shooter.
38	John W. Jones ..	Roadman.
39	Hugh Ransome ..	
40	Thomas Baker ..	Trucker.
41	Thomas Berry ..	
42	John Jackson ..	
43	John Martin ..	



A.E.W.