SECTION IV.—WORKING OF THE COAL-MINES ACT.

(a) PERMITTED EXPLOSIVES.

(Regulations 233 to 237 inclusive.)

The following is a table showing the quantity of permitted explosives used and the number of shots fired at New Zealand coal-mines during 1926:—

Inspection District.	Quantity of Permitted Explosives used (lb.).				Number of Misfired Shots.				Quantity
	A2 Monobel.	Ligdynite.	Samsonite.	Number of Shots fired.	By Defective Explosive.	By Defective Detonators.	By Defective Leads.	Total.	Approximate Qua
Northern (i.e., North Island) West Coast (of South Island) Southern (i.e., Canterbury, Otago, and Southland)	$\begin{array}{r} 83,770 \\ 175,508\frac{3}{4} \\ 24,382\frac{1}{2} \end{array}$	• •	$\begin{array}{c} 96,726\frac{1}{4} \\ 53,326\frac{1}{2} \end{array}$	102,520 327,105 110,289	:11	170 520 61*	14 205 18*	184 736 85	Tons. 340,558 1,103,967 241,358
Totals	$283,661\frac{1}{4}$		$150,052\frac{3}{4}$	539,914	11	751	237	1,005	1,685,883

^{*} Unaccounted for, 6.

Seventy-five per cent. of the coal produced in the Dominion during 1926 was broken down by permitted explosive, and the average production of coal per pound of explosive used was 3.88 tons, and per shot fired 3.13 tons.

(b) LIST OF MINES REQUIRED BY LAW TO USE PERMITTED EXPLOSIVES.

The following is a list of mines as at the 1st December, 1926, required by law to use permitted explosives:—

Northern Inspection District.

Pukemiro Collieries, Pukemiro-throughout South Mine.

Rotowaro Colliery, Rotowaro—throughout Nos. 1 and 3 Mines.

Glen Afton Colliery, Glen Afton—all sections of the mine with the exception of A section.

Waikato Extended Colliery, Huntly—throughout the mine.

West Coast Inspection District.

North Cape Mine.
Puponga Mine.
Westport-Stockton Mine.
Westport Coal Company's mines.
J. T. Dove's mine.
Coal Creek Mine (McGuire and party).
Cardiff Bridge Mine.
Old Cardiff (Clay Pit).
St. Helens Mine (McAllister and party).
Westport-Mokihinui Mine.
Chester and party's mine.
Marris and Murray's mine.
Ngakawau Mining Syndicate's mine.
Whitecliffs Mine.
Reefton Coal Company's mine.
Phœnix and Venus Mine.
Victory Mine (now Calliope).
Woodlands Mine.
Empire Mine.

Lankey's Creek Mine (Bolitho Bros.).

Ferndale-Timaru Coal Company's mine. Sherwood (now Morrisvale) Mine (Morris and Learmont). Paparoa Mine. Blackball Mine. Armstrong and party's mine. Baddeley and party's mine. Boote and party's mine. Dixon and party's mine. Clark and party's mine (Hillside). Duggan and party's mine. Hunter and party's mine. Manderson and party's nine. McIvor and party's mine. Moody Creek Mine (Simpson and party... Smith and party's mine. Spark and party's mine. James Mine. Liverpool Collieries.

Southern Inspection District.

Castle Hill Mine, Kaitangata—throughout the mine. Kaitangata No. 1 Mine, Kaitangata—throughout the mine. Kaitangata No. 2 Mine, Kaitangata—throughout the mine. Wairaki No. 1 Mine, Ohai—throughout the mine. Birchwood Mine, Ohai—throughout the mine. Linton No. 2 Mine, Ohai.

Ohai Coal Company's mine, Ohai.