

TABLE M.—APPENDIX I.

STATEMENT showing QUANTITY and STATE of ROLLING-STOCK on the MIDDLE ISLAND RAILWAYS on 30th June, 1878.

		CARRIAGES.												BRAKES.				
		1ST CLASS.				COMPOSITE.				2ND CLASS.								
		8 wheels, American Bogies.	6 wheels, end doors.	6 wheels, side doors.	6 wheels, Cleminson's radial axles.	4 wheels, end doors.	4 wheels, side doors.	8 wheels, American Bogies.	6 wheels, end doors.	6 wheels, side doors.	6 wheels, Cleminson's radial axles.	4 wheels, end doors.	4 wheels, side doors.					
CHRISTCHURCH.		1	11			1		25		10		35		9				26
In good order								2				5		1				2
Undergoing heavy repairs								1										
Undergoing light repairs																		
In course of erection		1														4		
In hands of contractors																		
Total		2	11			1		28		10		40		10		4		28
DUNEDIN.																		
In good order			5			8		9		4		24		21		4		7
Undergoing heavy repairs			1												1			
Undergoing light repairs								2				2						
In course of erection																		
In hands of contractors																		
Total			6			8		11		4		26		21		5		7
INVERCARGILL.																		
In good order			7			2		13				18		4		1		8
Undergoing heavy repairs								1				3				1		1
Undergoing light repairs																		
In course of erection																		
In hands of contractors																		
Total			7			2		14				21		4		2		9
BRUNNER.																		
In good order										2				2				2
Undergoing heavy repairs																		
Undergoing light repairs																		
In course of erection																		
In hands of contractors																		
Total										2				2				2
WESTPORT.																		
In good order						1								2				2
Undergoing heavy repairs																		
Undergoing light repairs																		
In course of erection																		
In hands of contractors																		
Total						1								2				2
NELSON.																		
In good order						1		1		2				2				2
Undergoing heavy repairs																		
Undergoing light repairs						1												
In course of erection																		
In hands of contractors																		
Total						2		1		2				2				2
PICTON.																		
In good order						1		2				1		1		2		
Undergoing heavy repairs																		
Undergoing light repairs																		
In course of erection																		
In hands of contractors																		
Total						1		2				1		1		2		
Grand Total		2	24			8		56		18		88		21	21	13		50