

RETURN of NOTICES given to REPAIR BOILERS—*continued.*

Number.	Type.	Description of Repairs.
1	Cornish tubular ...	Brickwork repaired.
1	Lancashire ...	New manhole-door fitted.
1	Locomotive ...	Firebox tube-plate renewed.
2	" ...	New firebox.
3	" ...	Retubed.
1	" ...	Manhole cut and door fitted; five stay-tubes fitted.
1	" ...	Three new tubes fitted.
1	" ...	Firebox-stays in throat-plate renewed.
1	" ...	Forty-three new tubes and four new mud-plugs fitted.
1	" ...	Patch on front renewed.
1	" ...	Bottom of barrel renewed.
1	" ...	Patch fitted round furnace-door.
1	" ...	Six new stays fitted to strengthen tube-plate.
1	" ...	Compensating-ring fitted round sludge-door.
1	" ...	Tubes expanded.
1	" ...	Six new screwed stays fitted in firebox.
1	" ...	Twelve new screwed stays fitted in firebox.
1	Marine ...	Five rings put round furnaces to strengthen them.
1	" ...	Bottom of combustion-chamber patched.
10	Multitubular ...	Retubed.
1	" ...	Back tube-plate patched.
11	" ...	Compensating-rings fitted round door-openings.
4	" ...	New manhole-doors fitted.
2	" ...	New sludge-doors fitted.
2	" ...	New studs in manhole-doors.
9	" ...	Patch fitted on bottom of shell.
1	" ...	Manhole-door repaired.
2	" ...	Manhole-door reriveted.
3	" ...	Top of steam-dome patched.
1	" ...	Patch fitted under blow-off cock.
2	" ...	Angle-iron ring riveted to manhole-door.
1	" ...	Doubling plate at manhole reriveted.
4	" ...	Patch fitted between safety-valve and boiler.
1	" ...	New crown in steam-dome.
1	" ...	New tube-plate.
1	" ...	Patch fitted over laminated plate.
2	" ...	Steam-space stays renewed.
1	" ...	Edge of sludge-hole in front tube-plate chipped round; new door, dog, and nut fitted.
2	" ...	Two rows of tubes drawn and boiler cleaned.
1	" ...	A number of rivets renewed.
2	" ...	Six new stay-tubes fitted.
1	" ...	Extra stay-tube fitted.
1	" ...	Fifteen stays fitted.
2	" ...	Front tube-plate patched.
1	" ...	Patch fitted under steam-dome.
1	" ...	Three new tubes fitted.
1	" ...	Part of furnace-crown cut out and patched.
1	" ...	Top row of tubes renewed, and patch fitted on bottom of shell.
1	" ...	Two new tubes and bolted patch on tube-plate.
25	Portable ...	Retubed.
1	" ...	New firebox.
48	" ...	Compensating-rings fitted to sludge-doors.
7	" ...	New sludge-doors.
13	" ...	A number of screwed stays renewed.
10	" ...	Crown-stays renewed.
5	" ...	New studs in sludge-doors.
1	" ...	Cross dogs fitted; patched along bottom and crown of firebox, patch fitted on barrel.
3	" ...	Tube-plate patched.
1	" ...	Thirty-eight new screwed stays fitted.
10	" ...	Steam-space stays renewed.
20	" ...	Firebox patched.
1	" ...	New firebox fitted; new girder-stays on crown; all new screwed stays; retubed; two new longitudinal stays.
4	" ...	Three new tubes fitted.
1	" ...	Two new main stays and two patches fitted.
1	" ...	Wheel-bracket taken off and patch fitted underneath.
1	" ...	Patch 16 in. by 10 in. put on under barrel.
1	" ...	Patch fitted on under pump.
1	" ...	Extra girder put on crown, and five new tubes.
1	" ...	All tubes drawn and boiler cleaned.
2	" ...	New girders and bolts fitted.