

No. 3.—RETURN of NOTICES given to REPAIR BOILERS—*continued.*

Number.	Type.	Description of Repairs.
1	Portable	Three new mud-doors and mudhole-openings fitted with compensating-rings.
1	"	Three new rivets in manhole-door.
2	"	Three new studs fitted in mud-doors.
1	"	Three new screwed stays fitted in firebox.
1	"	Three new screwed stays fitted in laminated plate in firebox.
2	"	Three new tubes fitted.
4	"	Tubes expanded.
3	"	Tubes in front end beaded.
1	"	Tube-plate patched.
1	"	Two girder-stays renewed.
1	"	Two longitudinal stays and seven new screwed stays fitted.
4	"	Two new longitudinal stays fitted.
1	"	Two new mud-doors.
1	"	Two new mud-doors, and compensating-rings fitted round mudhole-openings.
1	"	Two new rivets in foundation-ring.
1	"	Two new rivets in manhole compensating-ring.
2	"	Two new screwed stays fitted in firebox.
4	"	Two new screwed stays fitted in firebox, and compensating-rings to mudhole-openings.
1	"	Two new screwed stays fitted in throat-plate.
1	"	Two new tubes fitted.
3	"	Twenty new screwed stays fitted in firebox.
1	"	Twenty-three new screwed stays fitted in firebox.
1	Rectangular	Eighteen new screwed stays fitted.
1	Semi-portable	Five new longitudinal stays fitted.
1	"	Sight-hole cut, and tapered plug fitted.
1	"	Three mudhole-openings fitted with compensating-rings.
1	Semi-tubular	New stays fitted in crown.
1	"	Patch fitted on back tube-plate.
1	"	Patch to renew, and one new patch to fit on furnace.
1	"	Seven rivets renewed in furnace.
1	"	Shell patched on bottom.
1	"	Three new tubes fitted.
1	Traction	All new screwed stays fitted in firebox.
1	"	Compensating-ring fitted to manhole-opening.
3	"	Compensating-rings fitted to mudhole-openings.
1	"	Crack in firebox-crown, chain pinned.
2	"	Eight new tubes fitted.
1	"	Eighteen new tubes fitted.
1	"	Fifteen new tubes put in.
1	"	Firebox-crown repaired.
1	"	Five new screwed stays fitted in firebox.
1	"	Four new stay-tubes fitted.
2	"	Four new tubes fitted.
1	"	Front tube-plate renewed.
1	"	Leaky bar-stays rejointed.
1	"	New firebox fitted.
1	"	New firebox, retubed, all new screwed stays in firebox, patch riveted over front outside of firebox, and patch under fire-door.
4	"	New studs fitted in manhole-doors.
1	"	Nine new screwed stays fitted in firebox.
2	"	One new screwed stay put in firebox.
1	"	Patch fitted on bottom of barrel.
1	"	Patch fitted on crown of firebox.
6	"	Patches fitted on sides of firebox.
2	"	Patches in firebox renewed.
10	"	Retubed.
2	"	Retubed and new firebox fitted.
1	"	Retubed, new firebox-crown, and new tube-plate fitted.
1	"	Retubed, three new screwed stays in firebox.
1	"	Retubed, three new stay-tubes and forty-four new screwed stays fitted in firebox.
1	"	Retubed, twenty-nine new screwed stays fitted in firebox, and seven new rivets in front tube-plate.
2	"	Seven new tubes fitted.
1	"	Ten new girder-stays fitted on crown.
5	"	Ten new tubes fitted.
4	"	Three new screwed stays put in firebox.
6	"	Tubes expanded.
1	"	Twenty-one new tubes fitted.