

Fig. 4.


Diagram showing Auxiliary Base and Triangle Check
on the direct Measurement of Section No. 9.

OBSERVED ANGLES.

Bidwill	90° 49'	7.27"
IX	50° 35'	16.72"
X	38° 35'	35.09"
	<u>179° 59'</u>	<u>59.08"</u>

LINKS.

VIII - Bidwill	7251.7488	measured
VIII - IX	100.1362	"
IX - Bidwill	7151.6126	
Also IX - Bidwill	7151.6225	calculated from auxiliary base.
Difference	<u>0.0099</u>	



NOTE.—Angles observed by Mr. H. J. Lowe, District Surveyor,
using a 10 in. Everest Theodolite.