

No. 3.—RETURN OF NOTICES GIVEN TO REPAIR BOILERS, ETC.—*continued.*

Number.	Type.	Description of Repairs.
1	Portable	Retubed, new longitudinal stays fitted, and mudhole-opening compensated.
1	"	Retubed, one new door, and new crown in firebox.
10	"	Several new screwed stays fitted in firebox.
2	"	Several new tubes fitted.
1	"	Sight-hole cut in firebox, and six new screwed stays fitted.
1	"	Six stays fitted between crown of boiler and crown of firebox.
3	"	Sixteen new screwed stays fitted in firebox.
2	"	Ten new screwed stays fitted in firebox.
1	"	Ten new tubes fitted.
1	"	Thirty new screwed stays fitted in firebox.
1	"	Three new girders fitted on crown of firebox.
1	"	Three patches on firebox-shell renewed.
2	"	Twenty new screwed stays fitted in firebox.
1	"	Two additional girders and four bolts fitted over present girders on firebox-crown.
1	"	Two patches in firebox renewed.
1	"	Two rows of tubes renewed.
1	Semi-portable	All new screwed stays fitted in firebox.
1	"	Fifteen new screwed stays fitted in firebox.
1	"	One new longitudinal stay fitted.
1	"	Patches fitted in firebox.
1	"	Retubed.
1	"	Several rivets renewed in shell.
1	Semi-tubular	Blow-off cock taken off, and compensating-ring fitted on boiler-shell.
1	"	New firebox fitted.
1	"	Patch fitted on bottom of shell.
1	"	Patch renewed.
2	"	Retubed.
1	"	Retubed, and patch fitted on crown of boiler.
1	"	Stay-tubes renewed.
1	"	Two new stay-nuts fitted.
1	Traction	All new screwed stays fitted in firebox.
1	"	Compensating-ring fitted to manhole-opening.
5	"	Compensating-rings fitted to mudhole-openings.
1	"	Compensating-ring fitted to mudhole-opening, and new tapered mud-plug in front tube-plate.
1	"	Compensating-ring fitted to mudhole-opening, and pigot to manhole-door.
1	"	Crack cut out of side of firebox, and patch fitted.
1	"	Eight rivets renewed in tube-plate.
1	"	Fifteen new screwed stays fitted in firebox.
1	"	Fusible plug-hole enlarged, and new plug fitted.
1	"	Girders on crown of firebox repaired.
1	"	New dogs for manhole-door.
1	"	New firebox fitted.
1	"	New firebox and new tubes fitted.
2	"	New mud-doors fitted.
3	"	Patch fitted on crown of firebox.
1	"	Patch fitted on crown of firebox at fusible plug-hole, and several screwed stays renewed.
1	"	Patch fitted on firebox outside, new coupling-pins in longitudinal stays, new studs and dogs for manhole-door.
1	"	Patch on bottom of throat-plate enlarged, patch fitted on back head-plate, and seven new screwed stays
1	"	Patch on firebox-crown renewed, and mudhole-opening compensated.
1	"	Patch on firebox renewed, four new screwed stays in throat-plate, and two new coupling-pins in diagonal stays.
2	"	Plug-holes re-tapped, and new tapered plugs fitted.
6	"	Retubed.
1	"	Retubed, and patch on tube-plate.
1	"	Seven new tubes and two new mud-doors.
5	"	Several new screwed stays fitted in firebox.
2	"	Several new tubes fitted.
1	"	Shell under blow-off cock patched, and new mud-door fitted.
2	"	Studs in manhole-door renewed.
1	"	Ten new tubes fitted.
1	"	Two new cross-girders and four stays in crown.
1	"	Two new nuts fitted to crown-stays, and fusible plug-hole enlarged.