

TABLE D.—LIST OF EXHIBITS.

Exhibit
No.

1. Book of various reports.
2. Sir John Coode's plan.
3. Mr. Culcheth's plan.
4. Extract from minute-book of that period, 1882.
5. Goodall's plans (in five parts).
6. Marchant's report.
7. Marchant's plan.
8. Nelson's report and plan (printed pamphlet).
9. Maxwell, Williams, and Mason's report.
10. Transcript of oral report, Mr. Ferguson.
11. Kennedy's report on soundings.
12. Finch's report on soundings.
13. Plan of Kennedy's soundings.
14. Cullen and Keele's report, 1912.
15. Cullen and Keele's plans (three).
16. Questions to, and answers by, Cullen and Keele.
17. Cable to Cullen and Keele, and their reply.
18. Plan submitted under Harbour Act, with application for special Act, 1914.
19. Furkert's report, 1924.
20. Plan with Mr. Furkert's report, with graphs (five sheets).
21. Cullen and Keele's 1925 report.
22. Cullen and Keele's plans (three).
23. Plan of borings supplied to Cullen and Keele: Ground plan by Pengelly; individual reports on each bore by Pengelly; graphs and plans (twelve in all).
24. Minutes as to Mr. Keele's advice. . . . checking borings.
25. Extract from p. 530, minute-book, 4/5/25.
26. Plans of soundings by Holmes and Son, 1927.
27. Letter, Harbour Board to Marine Department, and reply to Board, 14/4/26.
28. Comparative lighterage and wharfage costs.
29. Return cost of labour on general cargo at breakwater shed.
30. Statement of charges by New Zealand Railways for haulage and delivery charges at various ports in New Zealand.
31. Dissection of total costs, Wellington to Dannevirke and Napier to Dannevirke.
32. Railway rates.
33. Statement valuation and population, rating district.
34. Dredging return covering seventeen years.
35. Statement of published accounts for 1923.
36. Statement of published accounts for 1926.
37. Return showing liners using roadstead for two years.
38. Return showing liners using breakwater for two years.
39. Return showing coastal boats and liners using Inner Harbour.
40. Return showing berthage rates, 1924 to 1/7/1927.
41. Return showing amount of aggregate berthage paid, cargo landed and shipped, and cost per ton.
42. Report by D. N. Campbell (on reclamation).
43. Plan accompanying Campbell's report.
44. Report by Hay and Rochfort of 8/5/26 (on reclamation).
45. Five plans (a), (b), (c), (d), and (e) accompanying Exhibit No. 44 (on reclamation).
- 46, 46A. Report of Hay and Rochfort of 4/10/26 (on reclamation).
47. Report by Holmes and Son (on reclamation).
48. Report by George Nelson, June, 1922 (on reclamation).
49. 1927 Empowering and Loan Bill.
50. List of vessels drawing 20 ft. or upwards.
51. Election propaganda sent out by Board in 1920.
52. Copy of letter to P. F. Higgins, 18/7/24, from Secretary, Harbour Board.
53. Set of shipping documents.
54. Bills of lading, showing alteration of destination.
55. Two bundles of letters (seven letters, 2/3/26 to 1/10/26, and ten letters, 2/3/26 to 3/8/26), put in by P. F. Higgins.
56. Copies letters, Harbour Board and Canadian Government Marine Board.
57. Lists of soundings at Inner Harbour (ten bundles, April, 1924, to June, 1927).
58. Return of quarrying-costs.
59. Report of C. D. Kennedy on the flooding problem.
60. Return of cargo imported, 1/7/25 to 31/6/27.
61. Cost of handling cargo at breakwater.

Exhibit
No.

62. Return of coastal and intercolonial vessels at breakwater, two years, 1/7/25 to 30/6/27.
63. Return of coastal and intercolonial vessels at Inner Harbour.
64. Comparative statements, charges various Harbour Boards.
65. Statement, charges various New Zealand ports on vessels, 2,321 tons net register.
66. Locality map of Hawke's Bay.
67. Litho map showing coloured shoal patch near breakwater.
68. Report of Holmes and Son to Harbour Board on shoaling.
69. Photograph (1887) of West Shore.
70. Plan showing shore-line at various periods.
71. Jar of material from bore 85 or 86.
72. Tin of sample of bottom at Whakariri patch.
73. Blue-print plan accompanying Cullen and Keele's 1925 report.
74. Plans of Glasgow Wharf (five plans).
75. Particulars of reclaimed sections offered for sale (see Chairman's report for 1926).
76. Piece of rock from foundation of breakwater.
77. Plan of borings by Holmes and Son—Inner Harbour; two plans.
78. Plan of subdivision of suggested early reclamation.
79. Plan of leases for sale by auction, 22/12/24.
80. Blue-print, breakwater, showing reclamation area for leasing (it accompanied Cullen and Keele's 1925 report).
81. Large plan of Napier Harbour.
81. (a), (b), (c), (d), (e), (f), (g), (h). Supplementary plans.
82. Report, Dominion Royal Commission on Harbours.
83. Three jars material from soundings—bore 41-38 and one unidentified.
84. Statement of areas to be reclaimed, and estimated values.
85. Plan of dredging by Browning crane.
86. Sample of bottom where blasting was required.
87. Correspondence *re* silt in Breakwater Harbour.
88. Return of accidents (both harbours).
89. Statement of Fruitgrowers' Association.
90. Plans, Mr. Napier Bell, accompanying his report of December, 1899.
91. Plan of Brisbane Harbour entrance.
92. Copies of minutes of Harbour Board.
93. Report of engineer *re* state of breakwater wharf.
94. List of loadings in roadstead; time occupied: (a), (b), (c), (d), (e), (f), (g), (h) attached (McLeay's return).
- 95 to 99 (inclusive). General questions submitted to and answered by Board's Secretary.
100. Photograph of breakwater in a storm.
101. Blue-print of tide-levels.
102. Plan of soundings.
103. Plan of roadstead.
104. Plan of soundings on beacon line.
105. Plan of soundings (west beach) on roadstead.
106. River diagram prepared by Mr. Furkert.
107. Tracing from Exhibit No. 26.
108. Graphs made up from soundings.
109. Plan of cross sections, West Beach.
110. Rough graph showing ratio of increase of siltation.
111. (a), (b), (c), (d), (e) contour maps (underwater).
112. Tracing from Admiralty chart, Napier Harbour.
113. Diagram showing depths water on bar (nineteen years).
114. Diagram showing tidal levels.
115. Wind diagram (three years).
116. Tracing of Admiralty chart, Colon Harbour.
117. (a), (b). List of ports visited by Mr. Furkert.
118. Tide-table for August, 1927, at Napier.
119. Longitudinal and lateral sections over dredged patch.
120. Sketch of type of cutter for dredge.
121. Tracing, comparative sections of outer channels.
122. (a), (b). Mr. Furkert's estimates of costs.
- 122½. Land-agent's plan.
123. Marine Department Report, 1924.
124. Plan No. 4037, submitted to Marine Department.
125. Letter, 4/6/27, Harbour Board to Auditor-General (bound in with notes).
126. Map showing Napier Harbour district.
127. Reclamation plan, showing pumping-stations.
128. Subdivision plans, Richmond Block.