

PLATE 2.
CROSS SECTIONS OF WOOD.



FIG. I. Cross sections of Corsican Pine. Sap stain did not develop seriously until after three months of summer weather. The right-hand section is typical of the sap stain at three months, the left-hand of sap stain at five months.




FIG. II. Cross sections of Austrian Pine (*Pinus austriacae*). Sap stain, at three months was slight, as shown in left-hand section. After three months the sap stain developed rapidly, as shown in the right-hand section.




FIG. III. Cross sections of European Larch (*Larix laricina*). Slight darkening of outer sapwood zone indicate slight sap stain.